

TPMS OE Sensors Application List

RDKS OE-Sensoren Verwendungsliste

(Status: 01.2022)



| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|---------------|-------------------------------|-------------------|----------------|---------------------|--|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeugmarke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| Alfa Romeo | Giulia | 05.2016 | | 50 547 691 | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0,4 Nm |
| Alfa Romeo | Stelvio | 12.2016 | | 50 547 691 | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0,4 Nm |
| BMW | 1-series (F20, F21) | 03.2014 | 11.2019 | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |
| BMW | 2-series (F22, F23, F45, F46) | 03.2014 | 11.2021 | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |
| BMW | 3-series (F30,F31,F34) | 03.2014 | 10.2018 | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |
| BMW | 4-series (F32, F33, F36) | 03.2014 | 06.2021 | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |
| BMW | i3 (I01) | 08.2013 | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |
| BMW | i8 (I12) | 03.2014 | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0,4 Nm |

| Car Brand | Model | from year onwards | by month/year | | OE Number of Sensor | Marking on Sensor | Order Number Replacement | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|----------------|---------------------|-------------------|----------------|---------------------|--------------------------|--|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| BMW | M2 (F87) | 11.2015 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | M3 (F80) | 04.2014 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | M4 (F82, F83) | 04.2014 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | X1 (F48) | 07.2015 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | X2 (F39) | 11.2017 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | X5 (F15, F85) | 05.2013 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| BMW | X6 (F16, F86) | 08.2014 | | | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| Chrysler | C200 | 03.2014 | 12.2016 | 4), 5) | 53 394 085 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Chrysler | Pacifica | 03.2016 | | 4), 5) | 53 394 085 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Citroen | C4 Aircross | 04.2014 | 04.2017 | | 1612477080 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Citroen | C-Zero | 10.2014 | | from Org.-Nr: 13749 | 1612477080 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Dodge | Durango | 10.2010 | | 4), 5) | 53 394 085 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Dodge | Dart | 10.2016 | | 4), 5) | 53 394 085 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Fiat | 124 Spider | 03.2016 | | 3) LL3 + LAB | BHB6-37140 | A2C11324100, A2C11324101 | A2C1132410180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Ford | Galaxy (WA6) | 05.2006 | 04.2015 | | 8G92 1A189-KB | S180052020 | S180084730Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Ford | S-Max (WA6) | 05.2006 | 04.2015 | | 8G92 1A189-KB | S180052020 | S180084730Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Ford | Mondeo IV (BA7) | 03.2007 | 12.2014 | | 8G92 1A189-KB | S180052020 | S180084730Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Honda | Accord | 07.2013 | | | 42753-TL0-G520 | S180052059 | S180052059Z | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Honda | Jazz | 11.2014 | 12.2015 | | 42753-TL0-G520 | S180052059 | S180052059Z | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Accent/Solaris (RB) | 08.2014 | 04.2017 | 7) | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Accent/Solaris (YC) | 04.2017 | | 7) | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Elantra (AD) | 01.2016 | | | 52933-F2000 | A2C98607702 | A2C9860770280 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Genesis (DH) | 01.2014 | | | 52933 2J100 | A2C99537900 | A2C9953790080 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Grand Santa Fe (NC) | 05.2013 | 03.2018 | | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Grandeur (HG, IG) | 03.2014 | | | 52933 D4100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | H-1 (TQ) | 12.2014 | | | 52933-4H100, 52940-4F100 | S180052072 | 2910000196000 | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | IONIQ Hybrid | 06.2016 | | | 52933 D4100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | i20 (PB/PBT) | 08.2008 | 06.2014 | | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | i20 MY 2012 (PB) | 06.2014 | EOP | | 52933 2M650 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | iX20 (JC) | 11.2010 | 05.2013 | | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | iX20 (JC) | 05.2013 | | | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | i30 (GD) | 11.2011 | 12.2016 | | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | i30 (PDE) | 12.2016 | 07.2018 | 7) | 52933-F2000 | A2C98607702 | A2C9860770280 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | i30N (PDE) | 08.2017 | | | 52933-F2000 | A2C98607702 | A2C9860770280 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Kona (OS) | 09.2017 | | | 52933-F2000 | A2C98607702 | A2C9860770280 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Hyundai | Santa Fe (DM) | 08.2012 | 08.2018 | | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Infiniti | Q50 | 04.2013 | | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Infiniti | Q60 | 10.2013 | | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |

| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|----------------|-------------------------------|-------------------|----------------|--------------------------|--------------------------------------|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| Infiniti | QX60 | 09.2013 | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | X-Type (X400) | 01.2007 | 12.2009 | C2Z31510 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | I-Pace (EV400) | 05.2018 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | F-Type (X152) | 10.2012 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | F-Pace (X761) | 12.2015 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | E-Pace | 09.2017 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XE (X760) | 02.2015 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XF (X250) | 03.2008 | 06.2015 | C2Z31510 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XF (X260) | 06.2015 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XJ (X350) | 05.2003 | 09.2009 | C2Z31510 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XJ (X351) | 10.2009 | | C2D47173 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | XK (X150) | 03.2006 | 07.2014 | C2Z31510 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jaguar | S-Type | 04.2002 | 08.2007 | C2Z31510 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Jeep | Renegade | 12.2014 | 4), 5) | 53305555 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Jeep | Compass (MK50) | 12.2016 | 4), 5) | 53 394 085 | A2C99154501 | A2C9915450180 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Jeep | Grand Cherokee (WK2 - MY2017) | 04.2016 | | 50 547 691 | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Carens (UN) | 12.2006 | 02.2013 | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Carens (RP/RP PE) | 03.2013 | | 52933 2J100 | A2C99537900 | A2C9953790080 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Cee'd (JD) | 03.2012 | 06.2018 | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Niro | 04.2016 | | 52933 D4100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Optima Hybrid | 03.2012 | 08.2013 | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Optima (TF) | 08.2013 | 06.2015 | 52933 2M650 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Optima Hybrid (TFe) | 03.2014 | 06.2015 | 52933 2M650 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Optima (JF) | 08.2015 | | 52933 D4100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Picanto (TA) | 04.2014 | 11.2016 | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Rio (YB) | 01.2017 | 3) | 52933 2J100 | A2C99537900 | A2C9953790080 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Sorento | 11.2009 | 09.2012 | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Sorento (XM) | 07.2012 | 09.2017 | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Sorento (UM) | 10.2014 | | 52933 2J100 | A2C99537900 | A2C9953790080 | 2910000307500 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Soul (AM) | 02.2009 | 12.2013 | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Soul (SK3) | 02.2018 | | 52933 D4100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Sportage (QL) | 10.2015 | | 52933 D9100 | A2C98607301 | 2910000102400 | A2C59507828 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Venga (YN) | 02.2010 | 04.2014 | 52933 1J000 | S180052012 | S180084710Z | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Kia | Venga (YN) | 04.2014 | | 52933 3N100, 52933 B1100 | A2C14467700 | A2C1446770080 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Lada | Granta | 04.2015 | 06.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Lada | Granta | 07.2016 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Lada | Kalina | 10.2016 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Lada | Vesta | 11.2015 | | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Land Rover | Discovery 3 (L319) | 07.2004 | 09.2009 | LR086928 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Land Rover | Discovery 4 (L319) | 09.2009 | 03.2017 | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |

| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core | |
|----------------|--------------------------------|-------------------|----------------|---------------------|--------------------------------------|---------------------------------------|---------------------------|------------------------------|-------------|-------------------------------|------------------------------|--------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz | |
| Land Rover | Discovery 5 (L462) | 04.2017 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Discovery Sport (L550) | 10.2014 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | FreeLander (L359) | 10.2006 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover (L322) | 2005 | 08.2009 | LR086928 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover (L322, L405) | 09.2009 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover Evoque (L538) | 09.2011 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover Sport (L320) | 2005 | 04.2010 | LR086928 | S180052080 | S180052080Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover Sport (L320, L494) | 05.2010 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Land Rover | Range Rover Velar (LY) | 09.2017 | | LR070840 | S180052076, S180052076B, A2C93315301 | S180052076Z | S180084520A | A2C59517073 | TG1C | 8 Nm | 0.4 Nm | |
| Maserati | Ghibli (M157) | 10.2018 | | | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm | |
| Maserati | Levante (139) | 10.2018 | | | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm | |
| Maserati | Quattroporte (M156) | 10.2018 | | | A2C97145802 | A2C9714580280 | A2C59507829 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm | |
| Mazda | 2 (DE) | 10.2008 | 06.2015 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | 3 (BL) | 06.2009 | 03.2013 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | 3 (BP) | 08.2018 | | | BDEL-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | 5 (CW) | 09.2010 | 09.2015 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | 6 (GH) | 08.2007 | 07.2013 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | 6 (GJ/GL) | 06.2017 | | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | CX-30 (DM) | 04.2019 | | | BDEL-37140, BDMC-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | CX-5 (KE) | 11.2011 | 05.2017 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | CX-5 (KF) | 06.2017 | | 3) | BHB6-37140, BDMC-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | CX-7 (ER) | 06.2009 | 12.2012 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | CX-9 (TB) | 08.2010 | 12.2015 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | MX5 (NC) | 03.2010 | 12.2014 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | MX5 (ND) | 04.2015 | | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | MX5 (NC) | 03.2010 | 12.2014 | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mazda | MX5 (ND) | 04.2015 | | 3) | BHB6-37140 | A2C19397601, A2C19397602 | A2C1939760180 | A2C59507828 | A2C59517073 | TG1C | 8 Nm | 0.4 Nm |
| Mercedes Benz | Citan / T-Class (W420) | 10.2021 | | | A 420 401 2400 | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| MINI | Cooper (F55, F56) | 3.2014 | | 6) | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| MINI | One (F55, F56) | 3.2014 | | 6) | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| MINI | Clubman (F54) | 07.2015 | | 6) | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| MINI | Cabrio (F57) | 03.2016 | | 6) | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |
| MINI | Countryman (F60) | 07.2015 | | 6) | 36 10 6 881 890 | A2C97432500, A2C97432501, A2C97432502 | A2C9743250080 | 2910000301700 | A2C59517073 | TG1C EVO | 8 Nm | 0.4 Nm |

| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|----------------|-----------------------|-------------------|--------------------|---------------------|--------------------------|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| Mitsubishi | ASX (ZC) | 08.2014 | | 4250C477 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Mitsubishi | i-Miev (TQ) | 07.2014 | | 4250C477 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Mitsubishi | Lancer (GS41) | 08.2014 | | 4250C477 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Mitsubishi | L200/Triton (CR) | 08.2014 | 4), 5) | 4250F1871 | A2C37819407 | A2C3781940780 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Mitsubishi | Outlander (RE) | 07.2014 | | 4250C477 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Mitsubishi | Pajero (BK) | 07.2014 | 4), 5) | 4250C275 | A2C37819407 | A2C3781940780 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Mitsubishi | Pajero Sport (QE) | 01.2016 | 4), 5) | 4250C275 | A2C37819407 | A2C3781940780 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Mitsubishi | Spacestar (EL) | 07.2014 | 4), 5) | 4250C275 | A2C37819407 | A2C3781940780 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Mitsubishi | Eclipse Cross | 01.2018 | 4), 5) | 4250C275 | A2C37819407 | A2C3781940780 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Altima (L33) | 03.2014 | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Micra (K14) | 12.2016 | 4), 5) | 407004CB0B | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Murrano (Z51) | 10.2014 | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Note (E12) | 08.2013 | | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | e-NV200 | 05.2014 | 09.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | e-NV200 | 10.2016 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Pathfinder (R51, R52) | 06.2013 | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Pulsar (C13) | 10.2014 | 09.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Pulsar (C13) | 10.2016 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Qashqai (J11) | 12.2013 | 09.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Qashqai (J11) | 10.2016 | 08.2021 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Tiida (C12) | 10.2014 | 09.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Tiida (C12) | 10.2016 | 07.2020 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | X-Trail (T32) | 11.2013 | 09.2016 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | X-Trail (T32) | 10.2016 | 04.2020 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Teana (J33) | 09.2013 | | 407003JA0B | S180052036 | S180052036Z | A2C59507830 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Nissan | Leaf (Gen2) | 01.2018 | 4), 5) | 407004CB0B | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Juke II | 09.2019 | 4), 5) | 407004CB0B | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Nissan | Juke III (F16E) | 01.2022 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Nissan | Ariya | 03.2022 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Nissan | Qashqai (J12) | 09.2021 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Nissan | X-Trail | 05.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Nissan | Tiida | 08.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Nissan | Townstar | 10.2021 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Peugeot | 4008 | 11.2014 | | 1612477080 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Peugeot | ION | 10.2014 | from Org-Nr: 13749 | 1612477080 | S180052094 | S180052094Z | A2C59507087 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Espace V | 06.2015 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Fluence | 02.2010 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Kadjar | 06.2015 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Koleos | 12.2013 | 03.2015 | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Koleos II | 08.2016 | | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Alpine (A110) | 01.2018 | | 407003VU0B | A2C82208303, A2C82208304 | A2C8220830480 | A2C59506227 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Laguna III | 10.2007 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |

| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|----------------|---------------------|-------------------|----------------|----------------------------------|--------------------------|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| Renault | Latitude | 02.2011 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Megane III | 11.2008 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Megane IV | 11.2015 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Scenic III | 02.2009 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Scenic IV | 09.2016 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Spider | 03.2010 | | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Talisman | 06.2015 | 4), 5) | 407004CB0A | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Zoe | 09.2012 | 08.2019 | 40 70 004 35 R | S180052064 | S180052064Z | S180084500A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Renault | Zoe II | 09.2019 | 4), 5) | 40700 4CB0B | A2C99668703, A2C99668705 | A2C9966870380 | 2910000063400 | - | TG1D | - | 0.4 Nm |
| Renault | Kadjar Gen 2 | 02.2021 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Megane IV Facelift | 10.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Megane e-Tech | 10.2021 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Espace Gen2 | 10.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Talisman ph2 | 07.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Kangoo Gen 3 | 09.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Trafic Gen 2 | 10.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Renault | Dokker Gen2 | 04.2020 | | 407006UA0A | A2C19969003 | 2802003001180 | 2910000439900 | - | TG1D Evo | - | - |
| Suzuki | Across | 10.2020 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Alto | 06.2014 | 12.2017 | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Cultus | 09.2014 | 09.2020 | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Grand Vitara | 06.2014 | 01.2019 | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Ignis | 01.2017 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Jimny(Gen3) | 05.2018 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Jimny | 11.2014 | 04.2018 | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Swift | 04.2014 | 04.2017 | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Swift (RZ/AZ) | 05.2017 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Swift Sport (RZ/AZ) | 06.2018 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Baleno II | 06.2016 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | SX-4 | 06.2014 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | SX-4 S-Cross | 08.2013 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Suzuki | Vitara | 02.2015 | | 43139-61M00, 43130-52S01 | S180052024 | S180052024Z | S180084510A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model S MY 2015 | 09.2014 | 06.2021 | 1034602-00-C | A2C10261600 | A2C1026160080 | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model S MY 2015 | 09.2014 | 06.2021 | Black valve stem 1074812-00-B | A2C10262100 | A2C1026210080 | 2910000418500 | 2910000418100 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model X | 09.2015 | 06.2021 | 1034602-00-C | A2C10261600 | A2C1026160080 | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model X | 09.2015 | 06.2021 | Black valve stem 1074812-00-B | A2C10262100 | A2C1026210080 | 2910000418500 | 2910000418100 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model 3 | 07.2018 | 10.2020 | 1034602-00-C | A2C10261600 | A2C1026160080 | A2C59507831 | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Tesla | Model 3 | 07.2018 | 10.2020 | Black valve stem 1074812-00-B | A2C10262100 | A2C1026210080 | 2910000418500 | 2910000418100 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | C30 | 10.2006 | 3) | 31302096 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | C30 Electric | 12.2010 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | C70 | 03.2006 | 3) | 31302096 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | S40 | 01.2004 | 3) | 31302096 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | S60 | 01.2011 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |

| Car Brand | Model | from year onwards | by month/year | OE Number of Sensor | Marking on Sensor | Order Number Replacement Sensor | Order Number Service-Kit | Order Number Valve Stem only | Generation | Torque for nut | Torque for valve core |
|----------------|-------------------|-------------------|----------------|---------------------|----------------------|----------------------------------|---------------------------|------------------------------|------------|-------------------------------|------------------------------|
| Fahrzeug-marke | Modell (Baureihe) | ab Monat/Jahr | bis Monat/Jahr | OE Nummer Sensor | Kennzeichnung Sensor | Bestellnummer Aftermarket Sensor | Bestellnummer Service-Kit | Bestellnummer Ventilstamm | Generation | Drehmoment für Überwurfmutter | Drehmoment für Ventileinsatz |
| Volvo | S80L | 03.2006 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | S80 | 03.2006 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | V50 | 04.2004 | 3) | 31302096 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | V60 | 09.2010 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | V70 | 03.2006 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | XC60 | 05.2008 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |
| Volvo | XC70 | 02.2007 | 3) | 31341893 | S180052050 | S180052050Z | S180084520A | A2C59517072 | TG1C | 8 Nm | 0.4 Nm |

- 1) If a service kit for a sensor of type TG1B is needed for the Ford, Jaguar, Land Rover, Mazda or Volvo brand, use article number S180014561A.
- 2) If a service kit for a sensor of type TG1B is needed for the Hyundai brand, use article number S180014531A.
- 3) These vehicle models are only be equipped with direct tire pressure monitoring systems as option.
- 4) Max. designed speed of TG1D sensors: 200 km/h. Vehicle models with a maximum speed of more than 200 kph have to use a TG1C sensor instead.
- 5) Installation of sensors only in specifically approved OE and spare part rims.
- 6) Sensor also for John Cooper Works variants.
- 7) This vehicle is equipped with a indirect system in the EU. Import cars can still be equipped with a direct TPMS.

- 1) Sollte bei den Marken Ford, Jaguar, Landrover, Mazda oder Volvo ein Service-Kit für einen Sensor der Bauform TG1B benötigt werden, dann Artikelnummer S180014561A.
- 2) Sollte bei der Marke Hyundai ein Service-Kit für einen Sensor der Bauform TG1B benötigt werden, dann Artikelnummer S180014531A.
- 3) Diese Fahrzeuge sind ggfs. nur optional mit direktem Reifendruckkontrollsystem ausgestattet.
- 4) Bauartbedingte Höchstgeschwindigkeit für TG1D-Sensoren: 200 km/h. Fahrzeug-Motorisierungen mit einer zulässigen Höchstgeschwindigkeit von mehr als 200 km/h müssen alternativ einen TG1C Sensor verwenden.
- 5) Verbau von Sensoren nur in spezifisch freigegebenen OE und Ersatzteil-Felgen.
- 6) Sensor auch für John Cooper Works Varianten
- 7) Dieses Fahrzeug wird mit einem indirektem System ausgeliefert. Importfahrzeuge können noch mit direktem RDKS ausgeliefert werden.