

EOBD/OBDII Application

| Make | From | Harness Required |
|-----------------|-------------|-------------------------|
| Petrol vehicles | 2000/2001 | A2C59514447 |
| Diesel vehicles | 2004 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|------------|---|------------|---|--------------------------------|
| Alfa Romeo | 145 | 94 - 00 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 146 | 94 - 00 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 147 | 00 - 07 | Bosch 5.7 ABS, Bosch 5.7 VDC, Bosch 5.7 ABS/ASR/TC, Bosch 8 ABS, Bosch 8 ASR, Bosch 8 VDC | A2C59514447 |
| Alfa Romeo | 155 | 95 - 97 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 156 | 97 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 156 '02 | 02 - 05 | Bosch 5.7 ABS, Bosch 5.7 VDC, Bosch 5.7 ABS/ASR/TC | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 159 | 05 - | TRW / Lucas ABS/ESP | A2C59514447 |
| Alfa Romeo | 164 | 88 - 98 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 166 | 98 - 03 | Bosch 5.3 ABS, Bosch 5.3 TC ABS, Bosch 5.7 VDC | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 33 | 88 - 89 | Bosch 5.3 ASR ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | Brera | 05 - | TRW / Lucas ABS/ESP | A2C59514447 |
| Alfa Romeo | GT | 04 - | Bosch 5.7 ABS, Bosch 5.7 VDC, Bosch 8 ABS, Bosch 8 VDC | A2C59514447 |
| Alfa Romeo | GTV | 95 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | MiTo | 08 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Alfa Romeo | Spider | 95 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Alfa Romeo | Spider (939) | 07 - | TRW / Lucas ABS/ESP | A2C59514447 |
| Audi | 80/Cabrio/Coupe/Quattro | 94 - 96 | KWP1281 | A2C59514447 (with A2C59512079) |
| Audi | A2 | 01 - 06 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 97 - 03 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 04 - | CAN | A2C59514447 |
| Audi | A4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A4 | 04 - | CAN | A2C59514447 |
| Audi | S4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S4 | 04 - | CAN | A2C59514447 |
| Audi | A5 | 08 - | CAN | A2C59514447 |
| Audi | S5 | 08 - | CAN | A2C59514447 |
| Audi | A6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A6 | 04 - | CAN | A2C59514447 |
| Audi | S6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S6 | 04 - | CAN | A2C59514447 |
| Audi | Allroad Quattro | 01 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | Q5 | 09 - | CAN | A2C59514447 |
| Audi | Q7 | 06 - | CAN | A2C59514447 |
| Audi | A8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A8 | 04 - | CAN | A2C59514447 |
| Audi | R8 | 07 - | CAN | A2C59514447 |
| Audi | S8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S8 | 04 - | CAN | A2C59514447 |
| Audi | TT | 98 - 07 | KWP1281/KW2000 | A2C59514447 |
| Audi | TT | 07 - | CAN | A2C59514447 |
| Audi | 100 | 94 - 97 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| BMW | 1 Series (E81/E87) - 4 Cylinder | 04 - 03/07 | Teves MK 60E | A2C59514447 |
| BMW | 1 Series (E81/E87) - 6 Cylinder | 04 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 1 Series (E81/E82/E87/E88) - 4 Cylinder | 03/07 - | Teves MK 60E (CAN) | A2C59514447 |
| BMW | 1 Series (E81/E82/E87/E88) - 6 Cylinder | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 1 Series (F20) | 07/10 - | DSC | A2C59514447 |
| BMW | 3 Series (E36) | 90 - 98 | ABS uC 3 Channel, ABS ASC ITT, ABS/ASC 5, Bosch ABS DSC3, Teves MK 20 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E46) | 98 - 05 | ABS/DSC 5.7, Teves MK 20, Teves MK 60, Teves DSC III MK 60 | A2C59514447 (with A2C59512084) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|---------|---|---------------|---|--------------------------------|
| BMW | 3 Series (E90/E91/E92/E93) - 4 Cylinder | 05 - 03/07 | Teves MK 60E | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) - 6 Cylinder | 05 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) - AWD | 05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) - 4 Cylinder | 03/07 - | Teves MK 60E (CAN) | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) - 6 Cylinder | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) - AWD | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | 5 Series (E39) | 96 - 04 | ABS/ASC 5, ABS/ASC 5.7, ABS/DSC 5.7 | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E60/E61) | 04 - 09/05 | Bosch ABS DSC8 | A2C59514447 |
| BMW | 5 Series (E60/E61) | 09/05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | M5 (E60) | 04 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | Bosch ABS DSC8 (CAN) | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | M5 (E60) | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 5 Series (F07/F10/F11) | 01/09 - | DSC 10 | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 09/05 | Bosch ABS DSC8 | A2C59514447 |
| BMW | 6 Series (E63/E64) | 09/05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | M6 (E63/E64) | 05 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | 6 Series (F12) | 10/09 - | DSC | A2C59514447 |
| BMW | M6 (E63/E64) | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 7 Series (E38) | 94 - 02 | ABS 5, ABS/ASC 5, BOSCH ABS DSC3 | A2C59514447 (with A2C59512084) |
| BMW | 7 Series (E65) | 02 - 03/07 | ABS/DSC5.7 | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | ABS/DSC5.7 (CAN) | A2C59514447 |
| BMW | 7 Series (F01/F02/F04) | 06/07 - | DSC | A2C59514447 |
| BMW | 8 Series (E31) | 90 - 99 | ABS 5, ABS/ASC 5, BOSCH ABS DSC3 | A2C59514447 (with A2C59512084) |
| BMW | X1 (E84) | 09/08 - | DSC | A2C59514447 |
| BMW | X3 (E83) | 03 - | DSC 8 X-Drive | A2C59514447 |
| BMW | X3 (F25) | 06/09 - | DSC | A2C59514447 |
| BMW | X5 (E53) | 00 - 09/03 | ABS/DSC 5.7 | A2C59514447 |
| BMW | X5 (E53) | 09/03 - | DSC 8 X-Drive | A2C59514447 |
| BMW | X5 (E70) | 06 - | Bosch ABS DSCS8 Plus (CAN), Bosch EHB 3 | A2C59514447 |
| BMW | X6 (E71) | 08 - | Bosch ABS DSCS8 Plus (CAN), Bosch EHB 3 | A2C59514447 |
| BMW | Z3 (E36) | 96 - 03 | Bosch ABS DSC3, Teves MK 20 | A2C59514447 (with A2C59512084) |
| BMW | Z4 (E85/E86) | 03 - 06 | Teves DSC III MK 60, DSC MK60E5 | A2C59514447 |
| BMW | Z4/Z4M (E85/E86) | 06 - | Teves DSC III MK 60, DSC MK60E5 | A2C59514447 |
| BMW | Z4 (E89) | 01/08 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | Z8 (E52) | 00 - 03 | ABS/DSC 5.7 | A2C59514447 (with A2C59512084) |
| Citroen | Berlingo | 96 - 04 | Bosch 5.0 / 5,3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | C1 | 05 - 05 | Bosch 8 ESP | A2C59514447 (with A2C59512080) |
| Citroen | C1 | 05 - | Bosch 8 ABS | A2C59514447 |
| Citroen | C2 | 03 - 05 | Teves MK60 / MK70 | A2C59514447 (with A2C59512080) |
| Citroen | C2 | 03 - | Teves MK60.0 CAN / Teves MK70.1 CAN | A2C59514447 |
| Citroen | C3 | 02 - 05 | Bosch 5.7 ESP / Teves MK60 | A2C59514447 (with A2C59512080) |
| Citroen | C3 II | 05 - | Teves MK60.0 CAN / Teves MK70.1 CAN | A2C59514447 |
| Citroen | C4 | 04 - 05 | Bosch 5.7 ESP / Teves MK60 | A2C59514447 (with A2C59512080) |
| Citroen | C4 / C4 Picasso | 03 - | Bosch ABS 8.0 CAN / Bosch ESP 8.0 CAN | A2C59514447 |
| Citroen | C4 Grand Picasso | 09 - | Bosch ESP 8.1 CAN | A2C59514447 |
| Citroen | C5 | 00 - 05 | Bosch 5.7 ESP / Teves MK60 | A2C59514447 (with A2C59512080) |
| Citroen | C5 II | 04 - | Teves MK60 CAN | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|---------|--------------------------|---------|--|--------------------------------|
| Citroen | C6 | 05 - | TRW ESP VSC 440 | A2C59514447 |
| Citroen | C8 | 02 - 05 | Bosch 5.7 ESP / Teves MK60 | A2C59514447 (with A2C59512080) |
| Citroen | C8 | 06 - | Bosch ESP 8.0 CAN | A2C59514447 |
| Citroen | C Crosser | 07 - | Bosch ESP 8.1 CAN | A2C59514447 |
| Citroen | Dispatch/Jumpy | 95 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | Evasion | 97 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | Relay/Jumper | 97 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | Saxo | 98 - 03 | Teves MK 20E/IE ABS / Teves 4-GI (ITT 04-GI) ABS | A2C59514447 (with A2C59512080) |
| Citroen | Synergie | 97 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | Xantia | 98 - 02 | Bosch 5.3 ABS / Teves MK 20E/IE ABS | A2C59514447 (with A2C59512080) |
| Citroen | XM | 96 - 01 | Teves MK 20E/IE ABS | A2C59514447 (with A2C59512080) |
| Citroen | Xsara | 97 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Citroen | Xsara Picasso | 99 - 03 | Bosch 5.3 ABS / Bosch 5.7 ESP | A2C59514447 (with A2C59512080) |
| Fiat | 500 | 07 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Fiat | Barchetta | 96 - 00 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Bravo/Brava | 95 - 02 | Teves MK20 | A2C59514447 (with A2C59512975) |
| Fiat | Bravo '07 | 07 - | Bosch 8 ABS, Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Coupe | 96 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Croma | 93 - 96 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Croma '05 | 05 - | TRW / Lucas ABS | A2C59514447 |
| Fiat | Ducato | 94 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Ducato RST | 01 - | Bosch 5.3 ABS, Bosch 5.3 ASR ABS | A2C59514447 |
| Fiat | Idea | 01 - | Bosch 5.3 ABS, Bosch 5.3 ASR ABS, Bosch 8 ABS, Bosch 8 VDC | A2C59514447 |
| Fiat | Marea/Weekend | 96 - 99 | Lucas ABS | A2C59514447 (with A2C59512975) |
| Fiat | Marea/Weekend | 96 - 03 | Lucas EBC 430 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Multipla | 98 - 01 | Bosch 5.3 ABS, Bosch 5.7 VDC ABS | A2C59514447 (with A2C59512975) |
| Fiat | Multipla '02 | 02 - | Bosch 5.3 ABS, Bosch 5.7 VDC ABS | A2C59514447 |
| Fiat | Palio | 97 - 01 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Palio RST | 01 - 02 | Bosch 5.3 ABS | A2C59514447 |
| Fiat | Palio RST2 | 02 - | Bosch 5.3 ABS | A2C59514447 |
| Fiat | Panda '03 | 03 - | Bosch 8 ABS, Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Punto | 93 - 99 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Punto '99 | 99 - 03 | Bosch 5.3 ABS, Bosch 5.3 TC ABS | A2C59514447 (with A2C59512975) |
| Fiat | Punto '03 | 03 - 05 | Bosch 5.3 ABS, Bosch 8 ABS, Bosch 8 VDC ABS | A2C59514447 (with A2C59512975) |
| Fiat | Punto '05 (Grande Punto) | 05 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Fiat | Scudo | 97 - 01 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Seicento | 98 - 00 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Fiat | Stilo | 01 - 07 | Bosch 5.7 ABS, Bosch 5.7 VDC, Bosch 5.7 ABS/ASR/TC, Bosch 8 ABS, Bosch 8 VDC | A2C59514447 |
| Fiat | Ulysse | 97 - 02 | Bosch 5.3 ABS | A2C59514447 |
| Fiat | Ulysse '02 | 02 - 05 | Bosch 5.7 ABS | A2C59514447 |
| Ford | Cougar | 99 - 02 | ABS | A2C59514447 |
| Ford | Crown Victoria | 95 - 07 | ABS | A2C59514447 |
| Ford | Escort | 95 - 02 | ABS | A2C59514447 |
| Ford | Excursion | 00 - | ABS | A2C59514447 |
| Ford | Expedition | 97 - | ABS | A2C59514447 |
| Ford | Explorer | 96 - | ABS | A2C59514447 |
| Ford | E-Series | 97 - 08 | ABS | A2C59514447 |
| Ford | F-250 Light Duty | 97 - 02 | ABS | A2C59514447 |
| Ford | Fiesta | 96 - 07 | ABS | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|-------|--------------------------|---------|--|--------------------------------|
| Ford | Fiesta | 08 - | ABS | A2C59514447 |
| Ford | Focus I | 99 - 04 | ABS | A2C59514447 |
| Ford | Focus II | 04 - | ABS | A2C59514447 |
| Ford | Focus C-MAX | 02 - | ABS | A2C59514447 |
| Ford | Fusion | 02 - 08 | ABS | A2C59514447 |
| Ford | Fusion II | 09 - | ABS | A2C59514447 |
| Ford | F-Series Super Duty | 97 - | ABS | A2C59514447 |
| Ford | Galaxy | 00 - 06 | ABS | A2C59514447 |
| Ford | Galaxy | 06 - | ABS | A2C59514447 |
| Ford | Granada/Scorpio | 94 - 98 | ABS | A2C59514447 |
| Ford | GT | 05 - 06 | ABS | A2C59514447 |
| Ford | Ka | 96 - 08 | ABS | A2C59514447 |
| Ford | Ka II | 08 - | ABS | A2C59514447 |
| Ford | Street Ka | 03 - 08 | ABS | A2C59514447 |
| Ford | Kuga | 08 - | ABS | A2C59514447 |
| Ford | Maverick | 01 - 04 | ABS | A2C59514447 |
| Ford | Maverick 05 | 05 - | ABS | A2C59514447 |
| Ford | Mondeo III | 95 - 06 | ABS | A2C59514447 |
| Ford | Mondeo IV | 07 - | ABS | A2C59514447 |
| Ford | Puma | 97 - 01 | ABS | A2C59514447 |
| Ford | Ranger | 99 - 06 | ABS | A2C59514447 |
| Ford | S-Max | 06 - | ABS | A2C59514447 |
| Ford | Transit | 00 - 06 | ABS | A2C59514447 |
| Ford | Transit | 06 - | ABS | A2C59514447 |
| Ford | Transit / Torneo Connect | 02 - | ABS | A2C59514447 |
| Ford | WindStar | 96 - 04 | ABS | A2C59514447 |
| GM | Agila-A | 00 - 08 | Agila ABS | A2C59514447 |
| GM | Astra-F | 92 - 97 | Bosch 2E | A2C59514447 |
| GM | Astra-G | 98 - 04 | Bosch 5.3/5.4TC, ESP | A2C59514447 |
| GM | Astra-H | 04 - | Astra-H ABS/TC/ESP | A2C59514447 |
| GM | Calibra | 90 - 97 | Bosch 2E | A2C59514447 |
| GM | Combo | 02 - 06 | Bosch5.3/5.4TC, Bosch 8 | A2C59514447 |
| GM | Corsa-B | 97 - 01 | Bosch 5.3 | A2C59514447 |
| GM | Corsa-C | 01 -06 | Bosch5.3/5.4TC, Bosch 8 | A2C59514447 |
| GM | Corsa-D | 06 - | Corsa-D ABS/TC/ESP | A2C59514447 |
| GM | Frontera-A | 95 - 98 | Bosch 415 | A2C59514447 |
| GM | Movano | 04 - 06 | ABS EBC430 (Renault) | A2C59514447 |
| GM | Meriva-A | 03 - 08 | Bosch 8 | A2C59514447 |
| GM | Omega-B | 94 - 03 | Bosch 2SH, Bosch 5.3/5.4TC, ESP | A2C59514447 |
| GM | Signum | 01 - | EBC430 ABS/TC/ESP | A2C59514447 |
| GM | Speedster / VX220 | 01 - 06 | KH430 | A2C59514447 |
| GM | Tigra-A | 95 - 00 | ABS 4/4F, Bosch 5.3 | A2C59514447 |
| GM | Tigra-B | 05 - 08 | Bosch 8 | A2C59514447 |
| GM | Vectra-B | 96 - 01 | Bosch 415, Bosch 5 TC, KH430, Bosch5.3/5.4TC | A2C59514447 |
| GM | Vectra-C | 01 - | EBC430 ABS/TC/ESP | A2C59514447 |
| GM | Vivaro | 01 - 06 | ABS EBC430 (Renault) | A2C59514447 |
| GM | Zafira-A | 99 - 05 | Bosch5.3/5.4TC, Bosch 8 | A2C59514447 |
| GM | Zafira-B | 05 - | Zafira-B ABS/TC/ESP | A2C59514447 |
| Honda | Accord V | 93 - 98 | Honda ABS/TCS early | A2C59514447 (with A2C59514540) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|---------|---------------|---------|---|--------------------------------|
| Honda | Accord V | 93 - 98 | Honda ABS/TCS late | A2C59514447 (with A2C59514540) |
| Honda | Accord VI | 98 - 03 | Honda ABS/TCS early | A2C59514447 (with A2C59514540) |
| Honda | Accord VI | 98 - 03 | Honda ABS/TCS late | A2C59514447 (with A2C59514540) |
| Honda | Accord VII | 03 - 07 | Honda ABS/TCS late | A2C59514447 (with A2C59514540) |
| Honda | Civic VI | 95 - 01 | Bosch 5.0 ABS | A2C59514447 (with A2C59514540) |
| Honda | Civic VII | 01 - 05 | Bosch 5.0 ABS | A2C59514447 (with A2C59514540) |
| Honda | Civic VIII | 05 - | Bosch 5.0 ABS | A2C59514447 (with A2C59514540) |
| Honda | CR-V I | 95 - 02 | ABS/TCS early | A2C59514447 (with A2C59514540) |
| Honda | CR-V I | 95 - 02 | ABS/TCS late, ABS/VSA | A2C59514447 (with A2C59514540) |
| Honda | CR-V II | 02 - 06 | ABS/TCS early | A2C59514447 (with A2C59514540) |
| Honda | CR-V II | 02 - 06 | ABS/TCS late, ABS/VSA | A2C59514447 (with A2C59514540) |
| Honda | CR-V III | 07 - | ABS/TCS late, ABS/VSA | A2C59514447 (with A2C59514540) |
| Honda | FR-V | 04 - 09 | Bosch 5.0 ABS, ABS/TCS late, ABS/VSA | A2C59514447 (with A2C59514540) |
| Honda | Jazz I | 02 - 07 | ABS/TCS early | A2C59514447 (with A2C59514540) |
| Honda | Jazz I | 02 - 07 | ABS/TCS late | A2C59514447 (with A2C59514540) |
| Honda | Prelude V | 96 - 00 | ABS/TCS early | A2C59514447 (with A2C59514540) |
| Honda | Prelude V | 96 - 00 | ABS/TCS late | A2C59514447 (with A2C59514540) |
| Honda | S2000 | 99 - 09 | ABS/TCS early | A2C59514447 (with A2C59514540) |
| Hyundai | Accent | 94 - 00 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Accent II | 00 - | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Amica | 03 - | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Atos | 03 - | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Coupe | 96 - 02 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Coupe II | 01 - | ABS Bosch FTCS (KW2K) | A2C59514447 |
| Hyundai | Coupe II | 01 - | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Coupe II | 01 - | ABS Mando TC (Carb) | A2C59514447 |
| Hyundai | Elantra III | 00 - 06 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Getz | 02 - | ABS Bosch 8 (KW2K) | A2C59514447 |
| Hyundai | Matrix | 01 - 05 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Santa Fé | 01 - 07 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Sonata IV | 01 - 04 | ABS Bosch ASB/ESP (KW2K) | A2C59514447 |
| Hyundai | Terrecan | 01 - 07 | ABS HMC Mando (Carb) | A2C59514447 |
| Hyundai | Trajet | 00 - 08 | ABS Bosch FTCS (KW2K) | A2C59514447 |
| Hyundai | Tuscon | 04 - 09 | ABS Bosch FTCS (KW2K) | A2C59514447 |
| Jaguar | S-Type | 99 - 08 | ABS SCP, ABS CAN, ABS CAN XK | A2C59514447 |
| Jaguar | X-Type | 01 - 08 | ABS CAN, ABS CAN XK | A2C59514447 |
| Jaguar | XJ/XJR (X350) | 03 - 09 | ABS CAN XK, ABS DSC CAN | A2C59514447 |
| Jaguar | XK/XKR (X100) | 96 - 06 | ABS SCP, ABS DSC CAN | A2C59514447 |
| Jaguar | XK/XKR (X150) | 06 - | ABS CAN XK | A2C59514447 |
| Lancia | Dedra | 94 - 99 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Lancia | Delta | 96 - 00 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Lancia | Kappa | 94 - 01 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Lancia | Lybra | 99 - 06 | Bosch 5.3 ABS, Bosch 5.3 ASR ABS, TRW Lucas ESP ABS | A2C59514447 (with A2C59512975) |
| Lancia | Musa | 04 - 06 | Bosch 8 ABS, Bosch 8 VDC ABS | A2C59514447 |
| Lancia | Phedra | 02 - 06 | Bosch 5.7 ABS, Bosch 5.7 ESP | A2C59514447 |
| Lancia | Thesis | 02 - 06 | TRW / Lucas ABS | A2C59514447 |
| Lancia | Y | 96 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |
| Lancia | Ypsilon | 03 - 06 | TRW / Lucas ABC, TRW / Lucas ESP ABS | A2C59514447 |
| Lancia | Z | 96 - 02 | Bosch 5.3 ABS | A2C59514447 (with A2C59512975) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|-------------|--------------------------|----------------|-----------------------------|--------------------------------|
| Land Rover | Defender | 99 - 03 | Wabco D | A2C59514447 |
| Land Rover | Defender (L316) | 06 - | Wabco D | A2C59514447 |
| Land Rover | Freelander | 98 - 01 | Wabco D | A2C59514447 |
| Land Rover | Freelander | 01 - 06 | ABS Mk25 | A2C59514447 |
| Land Rover | Freelander II (L359) | 07 - | Teves MK23 E1 | A2C59514447 |
| Land Rover | Discovery II | 99 - 04 | Wabco D | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | Bosch 8 | A2C59514447 |
| Land Rover | Discovery IV(L319) | 10 | MY10 ABS/ESP | A2C59514447 |
| Land Rover | Range Rover (P38a) | 99 - 03 | Wabco D | A2C59514447 |
| Land Rover | Range Rover (L322) | 02 - 06 | Bosch 5.7 | A2C59514447 |
| Land Rover | Range Rover (L322) | 06 - 09 | Bosch 8 | A2C59514447 |
| Land Rover | Range Rover (L322) | 10 | MY10 ABS/ESP | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | Bosch 8 | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 10 | MY10 ABS/ESP | A2C59514447 |
| Lexus | GS II | 97 - 04 | ABS ABJ | A2C59514447 |
| Lexus | GS III | 05 - | ABS CAN | A2C59514447 |
| Lexus | IS | 98 - 05 | ABS ABJ | A2C59514447 |
| Lexus | IS II | 06 - | ABS CAN | A2C59514447 |
| Lexus | LS III | 01 - 06 | ABS ABJ | A2C59514447 |
| Lexus | LS III | 01 - 06 | ABS CAN | A2C59514447 |
| Lexus | LS IV | 06 - | ABS ABJ | A2C59514447 |
| Lexus | LS IV | 06 - | ABS CAN | A2C59514447 |
| Lexus | RX | 98 - 03 | ABS ABJ | A2C59514447 |
| Lexus | RX II | 04 - 09 | ABS CAN | A2C59514447 |
| Lexus | SC II | 01 - | ABS ABJ | A2C59514447 |
| Lexus | SC II | 01 - | ABS CAN | A2C59514447 |
| Mazda | 323 VI | 98 - 04 | Bosch ABS F-9141 | A2C59514447 |
| Mazda | 2 | 02 - 07 | Bosch ABS F-9141 | A2C59514447 |
| Mazda | 3 | 04 -08 | ABS CAN | A2C59514447 |
| Mazda | 5 | 05 - 08 | Bosch ABS F-9141 | A2C59514447 |
| Mazda | 5 | 05 - 08 | ABS CAN | A2C59514447 |
| Mazda | 6 | 02 - 08 | Bosch ABS F-9141 | A2C59514447 |
| Mazda | MX-5 II | 98 - 05 | Bosch ABS F-9141 | A2C59514447 |
| Mazda | MX-5 III | 05 - 08 | ABS CAN | A2C59514447 |
| Mazda | RX-8 | 03 - | Bosch ABS F-9141 | A2C59514447 |
| Mercedes | A Class (W168) | 98 - 03 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | A Class (W169) | 04 - | ESP 169 | A2C59514447 |
| Mercedes | B Class (W245) | 05 - | ESP 169 | A2C59514447 |
| Mercedes | C Class (W202) | 93 - 01 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | C Class (W203) | 00 - 09/03 | ESP Mk25 | A2C59514447 |
| Mercedes | C Class (W203) | 09/03 - 07 | ESP Mk25 (CAN) | A2C59514447 |
| Mercedes | CL Class (W215) | 99 - 06 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | CLK (W208) | 98 - 02 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | CLK (W209) | 02 - 04/04 | ESP Mk25 | A2C59514447 |
| Mercedes | CLK (W209) | 04/04 - 02 | ESP Mk25 (CAN) | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | SBC/ESP | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | SBC (CAN) | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | SBC (CAN) Brake Bleed | A2C59514447 |
| Mercedes | E Class (W210) | 95 - 03 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|---|--------------------------------------|---------|--|--------------------------------|
| Mercedes | E Class (W211) | 02 - | EHB FSG | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | Sensotronic BC | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | Sensotronic BC Brake Bleed | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | SBC/ESP | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | SBC (CAN) | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | SBC (CAN) Brake Bleed | A2C59514447 |
| Mercedes | G Class (W461) | 98 - 02 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | G Class (W463) | 98 - | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | M Class (W163) | 95 - 03 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | M Class (W164) | 05 - | ESP164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | ESP164 | A2C59514447 |
| Mercedes | S Class (W140) | 91 - 08 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | S Class (W220) | 98 - 05 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | S Class (W221) | 05 - | ABR | A2C59514447 |
| Mercedes | SL (R129) | 93 - 03 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | EHB FSG | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | Sensotronic BC | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | SBC/ESP | A2C59514447 |
| Mercedes | SL (R230) | 03 - 06 | SBC (CAN) | A2C59514447 |
| Mercedes | SLK (R170) | 91 - 04 | ABS / ASR / ETS/ ESP / BAS* | A2C59514447 (with A2C59512083) |
| Mercedes | SLK (R171) | 04 - | ESP Mk25 (CAN) | A2C59514447 |
| Mercedes | SLR (199) | 04 - | EHB FSG | A2C59514447 |
| Mercedes | SLR (199) | 04 - | Sensotronic BC | A2C59514447 |
| Mercedes | Sprinter (W901 / W902 / W903 / W904) | 95 - 02 | ABS / ASR / ETS/ ESP | A2C59514447 (with A2C59512082) |
| *For BAS (if present) try switch positions G2, D2, F2 | | | | |
| MINI | MINI (R50 / R52 / R53) | 00 - 07 | Teves MK 60, Teves DSC III MK 60 | A2C59514447 |
| MINI | MINI (R55 / R56 / R57 / R60) | 06 - | TRW EBC 450 | A2C59514447 |
| Nissan | 350Z | 03 - 09 | ABS 28 | A2C59514447 |
| Nissan | Almera II | 02 - 07 | ABS 28, ABS 2B | A2C59514447 |
| Nissan | Almera II | 02 - 07 | ABS CAN | A2C59514447 |
| Nissan | Almera Tino (V10) | 00 - 06 | ABS 28, ABS 2B | A2C59514447 |
| Nissan | Almera Tino (V10) | 00 - 06 | ABS CAN | A2C59514447 |
| Nissan | Micra (K11) | 92 - 02 | ABS 28 | A2C59514447 |
| Nissan | Micra (K12) | 03 - 07 | ABS CAN | A2C59514447 |
| Nissan | Micra C+C | 05 - 07 | ABS CAN | A2C59514447 |
| Nissan | Navara | 04 - | ABS 28 | A2C59514447 |
| Nissan | Note | 06 - | ABS 28 | A2C59514447 |
| Nissan | Note | 06 - | ABS CAN | A2C59514447 |
| Nissan | Primera (P12) | 02 - 08 | ABS 28 | A2C59514447 |
| Nissan | Qashqai | 07 - | ABS 28 | A2C59514447 |
| Nissan | X-Trail | 01 - 07 | ABS 28 | A2C59514447 |
| Nissan | X-Trail | 01 - 07 | ABS CAN | A2C59514447 |
| Peugeot | 107 | 05 - | Bosch 8 ABS | A2C59514447 |
| Peugeot | 1007 | 04 - 05 | Teves MK60 | A2C59514447 (with A2C59512080) |
| Peugeot | 1007 | 04 - | Teves MK60.0 CAN / Teves MK70.1 CAN | A2C59514447 |
| Peugeot | 106 | 96 - 04 | Teves 4-GI (ITT 04-GI) ABS / Teves MK 20E/IE ABS | A2C59514447 (with A2C59512080) |
| Peugeot | 107 | 05 - 05 | Bosch 8 ESP | A2C59514447 (with A2C59512080) |
| Peugeot | 206 | 98 - 05 | Teves MK 20E/IE ABS / Teves MK60 / Teves MK70 | A2C59514447 (with A2C59512080) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|---------|-------------------|---------|---|--------------------------------|
| Peugeot | 207 | 06 - | Teves MK70.1 CAN | A2C59514447 |
| Peugeot | 306 | 93 - 02 | Bosch 5.0 ABS / Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | 307 | 01 - 07 | Bosch 5.3 ABS / Bosch 5.7 ESP / Bosch 8 ESP | A2C59514447 (with A2C59512080) |
| Peugeot | 307 II | 04 - | Bosch ABS 8.0 CAN / Bosch ESP 8.0 CAN / Bosch ABS 8.1 CAN / Bosch ESP 8.1 CAN | A2C59514447 |
| Peugeot | 308 | 07 - | Bosch ABS 8.0 CAN / Bosch ESP 8.0 CAN | A2C59514447 |
| Peugeot | 406 | 95 - 03 | Bosch 5.0 ABS / Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | 407 | 05 - | TRW ESP VSC 440 | A2C59514447 |
| Peugeot | 407 | 05 - | TRW EBC 440 CAN | A2C59514447 |
| Peugeot | 605 | 96 - 00 | Bosch 5.0 ABS / Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | 607 | 00 - 03 | Bosch 5.3 ABS / Bosch 5.7 ESP | A2C59514447 (with A2C59512080) |
| Peugeot | 806 | 97 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | 807 | 02 - 05 | Bosch 5.7 ESP | A2C59514447 (with A2C59512080) |
| Peugeot | 807 | 05 - | Bosch ABS 8.0 CAN / Bosch ESP 8.0 CAN / Bosch ESP 8.1 CAN | A2C59514447 |
| Peugeot | 3008 | 09 - | Bosch ESP 8.1 CAN | A2C59514447 |
| Peugeot | 4007 | 07 - | Bosch ESP 8.1 CAN | A2C59514447 |
| Peugeot | 5008 | 09 - | Bosch ESP 8.1 CAN | A2C59514447 |
| Peugeot | Boxer | 97 - 01 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | Expert | 97 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Peugeot | Partner / Ranch | 96 - 03 | Bosch 5.3 ABS | A2C59514447 (with A2C59512080) |
| Renault | Avantime | 01 - 03 | Bosch 5.7 | A2C59514447 |
| Renault | Clio | 91 - 98 | Bosch 5.0 / Bosch 5.3/5.3T | A2C59514447 |
| Renault | Clio | 91 - 98 | EBC 430 | A2C59514447 |
| Renault | Clio II | 98 - 06 | Bosch 5.0 / Bosch 5.3/5.3T | A2C59514447 |
| Renault | Clio II | 99 - 06 | Bosch 8.0 | A2C59514447 |
| Renault | Clio II | 99 - 06 | Teves MK 60 | A2C59514447 |
| Renault | Clio II | 99 - 06 | ABS 8 | A2C59514447 |
| Renault | Clio III | 06 - | Bosch 8.0 | A2C59514447 |
| Renault | Clio III | 06 - | ABS 8 | A2C59514447 |
| Renault | Clio III | 06 - | ESP 8 | A2C59514447 |
| Renault | Espace IV | 02 - 06 | Teves MK 60 | A2C59514447 |
| Renault | Espace IV Phase 2 | 06 - | Teves MK 60 | A2C59514447 |
| Renault | Master II | 98 - 02 | EBC 430 | A2C59514447 |
| Renault | Megane | 98 - 03 | Bosch 5.0 / Bosch 5.3/5.3T | A2C59514447 |
| Renault | Megane | 98 - 03 | Bosch 5.7 | A2C59514447 |
| Renault | Megane II | 03 - | Bosch 8.0 | A2C59514447 |
| Renault | Megane II | 03 - | ABS 8 | A2C59514447 |
| Renault | Megane II | 03 - | ABS 8 v3.0 | A2C59514447 |
| Renault | Kangoo | 01 - | Bosch 8 ESP | A2C59514447 |
| Renault | Kangoo | 01 - | Bosch 8.0 | A2C59514447 |
| Renault | Laguna | 98 - 01 | Bosch 5.3/5.3T / Teves MK 20 | A2C59514447 |
| Renault | Laguna II | 01 - 07 | Teves MK 60 | A2C59514447 |
| Renault | Laguna II Phase 2 | 06 - 08 | Teves MK 60 | A2C59514447 |
| Renault | Laguna II Phase 2 | 06 - 08 | ABS 8 | A2C59514447 |
| Renault | Laguna II Phase 2 | 06 - 08 | ABS 8 v3.0 | A2C59514447 |
| Renault | Laguna III | 08 - | ESP 8160-04 | A2C59514447 |
| Renault | Modus | 04 - | ABS 8 | A2C59514447 |
| Renault | Scenic | 98 - 03 | Bosch 5.0 / Bosch 5.3/5.3T | A2C59514447 |
| Renault | Scenic | 98 - 03 | Bosch 5.7 | A2C59514447 |
| Renault | Scenic II | 03 - | ABS 8 v3.0 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|-------------|-----------------------|----------------|----------------------------|--------------------------------|
| Renault | Scenic II | 03 - | ABS 8 | A2C59514447 |
| Renault | Twingo | 92 - 07 | Bosch 5.0 / Bosch 5.3/5.3T | A2C59514447 |
| Renault | Twingo | 92 - 07 | EBC 430 | A2C59514447 |
| Renault | Trafic II | 01 - | EBC 430 | A2C59514447 |
| Renault | Vel Satis | 01 - | Teves MK 60 | A2C59514447 |
| Seat | Alhambra | 96 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Altea | 04 - | CAN | A2C59514447 |
| Seat | Arosa | 97 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Cordoba | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Ibiza | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 00 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 04 - | CAN | A2C59514447 |
| Seat | Toledo | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Toledo III | 04 - | CAN | A2C59514447 |
| Skoda | Fabia | 00 - 07 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Fabia II | 07 - | CAN | A2C59514447 |
| Skoda | Octavia | 96 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Octavia II | 04 - | CAN | A2C59514447 |
| Skoda | Roomster | 06 - | CAN | A2C59514447 |
| Skoda | Superb | 02 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Yeti | 10 - | CAN | A2C59514447 |
| Toyota | Auris | 07 - | ABS CAN | A2C59514447 |
| Toyota | Avensis | 98 - 03 | ABS ABJ | A2C59514447 |
| Toyota | Avensis II | 03 - 08 | ABS ABJ | A2C59514447 |
| Toyota | Avensis Verso | 01 - | ABS ABJ | A2C59514447 |
| Toyota | Aygo | 05 - | ABS ABJ | A2C59514447 |
| Toyota | Camry (XV20) | 96 - 01 | ABS ABJ | A2C59514447 |
| Toyota | Camry (XV30) | 01 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Celica VII | 99 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Corolla VIII (E110) | 97 - 02 | ABS ABJ | A2C59514447 |
| Toyota | Corolla IX (E120) | 02 - | ABS ABJ | A2C59514447 |
| Toyota | Corolla Verso | 04 - | ABS ABJ | A2C59514447 |
| Toyota | Hiace IV | 98 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Hilux | 97 - | ABS Aisin (4x4) | A2C59514447 |
| Toyota | Land Cruiser (J90) | 96 - 98 | ABS Aisin (4x4) | A2C59514447 |
| Toyota | Land Cruiser (J100) | 98 - 03 | ABS Aisin (4x4) | A2C59514447 |
| Toyota | Land Cruiser (J120) | 03 - | ABS ABJ / ABS Aisin (4x4) | A2C59514447 |
| Toyota | MR2 III (ZZW30) | 00 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Picnic I | 96 - 02 | ABS ABJ | A2C59514447 |
| Toyota | Previa I | 97 - 00 | ABS ABJ | A2C59514447 |
| Toyota | Previa II | 00 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Prius (NHW20) | 04 - 09 | ABS ABJ | A2C59514447 |
| Toyota | RAV4 I (XA1) | 97 - 00 | ABS ABJ | A2C59514447 |
| Toyota | RAV4 II (CA20W) | 00 - 06 | ABS ABJ | A2C59514447 |
| Toyota | RAV4 III (CA30W) | 06 - | ABS CAN | A2C59514447 |
| Toyota | Yaris I | 99 - 06 | ABS ABJ | A2C59514447 |
| Toyota | Yaris II | 06 - | ABS CAN | A2C59514447 |
| Toyota | Yaris Verso | 99 - 06 | ABS ABJ | A2C59514447 |
| Volvo | C70 Convertible/Coupe | 99 - 05 | ABS 1.1 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK ABS

| Make | Model | From/To | System | Harness Required |
|-------------|--------------------------|----------------|------------------|--------------------------------|
| Volvo | S40 | 04 - 06 | ABS 2 | A2C59514447 |
| Volvo | V50 | 03 - 08 | ABS 2 | A2C59514447 |
| Volvo | S60 | 01 - 05 | ABS 1 | A2C59514447 |
| Volvo | S70 | 99 - 00 | ABS 1 | A2C59514447 |
| Volvo | V70 | 99 - 00 | ABS 1 | A2C59514447 |
| Volvo | V70 | 00 - 07 | ABS 2 | A2C59514447 |
| Volvo | XC70 | 99 - 00 | ABS 1 | A2C59514447 |
| Volvo | XC70 | 00 - 06 | ABS 2 | A2C59514447 |
| Volvo | S80 | 99 - 06 | ABS 2 | A2C59514447 |
| Volvo | XC90 | 02 - 06 | ABS 2 | A2C59514447 |
| VW | Amorak | 10 - | CAN | A2C59514447 |
| VW | Beetle | 99 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Bora | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Bora | 05 - | CAN | A2C59514447 |
| VW | Cabrio | 95 - 02 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 92 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 05 - | CAN | A2C59514447 |
| VW | Corrado | 91 - 95 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | EOS | 05 - | CAN | A2C59514447 |
| VW | Eurovan | 99 - 03 | KWP1281/KW2000 | A2C59514447 |
| VW | Golf/GTI | 92 - 03 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Golf/GTI | 03 - | CAN | A2C59514447 |
| VW | Golf Plus | 05 - | CAN | A2C59514447 |
| VW | Jetta | 92 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Jetta | 05 - | CAN | A2C59514447 |
| VW | Lupo | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 94 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 05 - | CAN | A2C59514447 |
| VW | Phaeton | 03 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Polo | 98 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Scirocco III | 09 - | CAN | A2C59514447 |
| VW | Sharan | 95 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Touareg | 03 - 06 | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 07 - | CAN | A2C59514447 |
| VW | Touran | 03 - | CAN | A2C59514447 |
| VW | Transporter/Caravelle | 92 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Transporter/Caravelle T5 | 04 - | CAN | A2C59514447 |
| VW | Vento | 92 - 98 | KWP1281 / KW2000 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|------------|----------------------------|------------|---|--------------------------------|
| Alfa Romeo | 145 | 94 - 98 | TRW2 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | 145 | 94 - 00 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | 146 | 94 - 98 | TRW2 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | 146 | 95 - 00 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | 147 | 00 - 04 | Allied MY97 | A2C59514447 |
| Alfa Romeo | 147 | 00 - 07 | Siemens MY99 | A2C59514447 |
| Alfa Romeo | 156 | 97 - 02 | Allied MY97, Allied Signal, Allied Signal 2 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | 156 '02 | 02 - 05 | Siemens MY99 | A2C59514447 |
| Alfa Romeo | 159 | 05 - | TRW MY03 | A2C59514447 |
| Alfa Romeo | 166 | 98 - 03 | TRW MY97, TRW MY99 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | Brera | 05 - | TRW MY03 | A2C59514447 |
| Alfa Romeo | GT | 04 - | Siemens MY99 | A2C59514447 |
| Alfa Romeo | GTV | 95 - 98 | TRW2 Airbag w/pretensioners | A2C59514447 (with A2C5952975) |
| Alfa Romeo | GTV | 97 - 03 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Alfa Romeo | MiTo | 08 - | SIEMENS Airbag (EP-Proxi) | A2C59514447 |
| Alfa Romeo | Spider | 95 - 98 | TRW2 Airbag w/pretensioners | A2C59514447 (with A2C5952975) |
| Alfa Romeo | Spider (939) | 07 - | TRW MY03 | A2C59514447 |
| Audi | 80/Cabrio/Coupe/Quattro | 94 - 96 | KWP1281 | A2C59514447 (with A2C59512079) |
| Audi | A2 | 01 - 06 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 96 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 04 - | CAN | A2C59514447 |
| Audi | A4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A4 | 04 - | CAN | A2C59514447 |
| Audi | S4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| Audi | S4 | 04 - | CAN | A2C59514447 |
| Audi | A5 | 08 - | CAN | A2C59514447 |
| Audi | S5 | 08 - | CAN | A2C59514447 |
| Audi | A6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A6 | 04 - | CAN | A2C59514447 |
| Audi | S6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S6 | 04 - | CAN | A2C59514447 |
| Audi | Allroad Quattro | 01 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | Q5 | 09 - | CAN | A2C59514447 |
| Audi | Q7 | 06 - | CAN | A2C59514447 |
| Audi | A8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A8 | 04 - | CAN | A2C59514447 |
| Audi | R8 | 07 - | CAN | A2C59514447 |
| Audi | S8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S8 | 04 - | CAN | A2C59514447 |
| Audi | TT | 98 - 07 | KWP1281/KW2000 | A2C59514447 |
| Audi | TT | 07 - | CAN | A2C59514447 |
| Audi | 100 | 94 - 97 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| BMW | 1 Series (E81/E87) | 04 - 03/07 | MRS5 | A2C59514447 |
| BMW | 1 Series (E81/E82/E87/E88) | 03/07 - | MRS5 (CAN), ACSM (CAN) | A2C59514447 |
| BMW | 1 Series (F20) | 07/10 - | ACSM 4 | A2C59514447 |
| BMW | 3 Series (E30) | 91 - 93 | Driver Airbag (5WK4 060) | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E36) | 90 - 98 | ZAE BAE, ZAE2, MRS 1, MRS 2, MRS 3 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E36) | 91 - 93 | Driver Airbag (5WK4 060) | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E36) | 93 - 95 | 1 or 2 airbags (ZAE, BAE) | A2C59514447 (with A2C59512084) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|----------------------------|------------|---|--------------------------------|
| BMW | 3 Series (E46) | 98 - 05 | MRS 3, MRS 4 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E90/E91/E92/E93) | 05 - 03/07 | MRS5 | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 06 - 03/07 | ACSM | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | MRS5 (CAN) | A2C59514447 |
| BMW | 5 Series (E34) | 91 - 93 | Driver Airbag (5WK4 060) | A2C59514447 (with A2C59512084) |
| BMW | 5 series (E34) | 93 - 95 | 1 or 2 airbags (ZAE, BAE) | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E39) | 96 - 04 | ZAE BAE, ZAE2, MRS 1, MRS 2, MRS 3, MRS 4 | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E60/E61) | 04 - 03/07 | ACSM | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | MRS6 | A2C59514447 |
| BMW | 5 Series (F07/F10/F11) | 01/09 - | ACSM 3 | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 03/07 | ACSM | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | MRS6 | A2C59514447 |
| BMW | 6 Series (F12) | 10/09 - | ACSM | A2C59514447 |
| BMW | 7 Series (E32) | 91 - 93 | Driver Airbag (5WK4 060) | A2C59514447 (with A2C59512084) |
| BMW | 7 Series (E38) | 94 - 02 | ZAE BAE, ZAE2, MRS 1, MRS 2, MRS 3, MRS 4 | A2C59514447 (with A2C59512084) |
| BMW | 7 Series (E65) | 02 - 03/07 | Multi-bag system | A2C59514447 |
| BMW | 7 Series (F01/F02/F04) | 06/07 - | ACSM 3 | A2C59514447 |
| BMW | 8 series (E31) | 93 - 95 | 1 or 2 airbags (ZAE, BAE) | A2C59514447 (with A2C59512084) |
| BMW | 8 Series (E31) | 90 - 99 | ZAE BAE, ZAE2, MRS 1, MRS 2 | A2C59514447 (with A2C59512084) |
| BMW | X1 (E84) | 09/08 - | MRS | A2C59514447 |
| BMW | X3 (E83) | 03 - | MRS 4 Redesign | A2C59514447 |
| BMW | X3 (F25) | 06/09 - | ACSM 4 | A2C59514447 |
| BMW | X5 (E53) | 00 - | MRS 3, MRS 4 | A2C59514447 |
| BMW | X5 (E70) | 06 - | ACSM (CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | ACSM (CAN) | A2C59514447 |
| BMW | Z3 (E36) | 96 - 03 | MRS 3, MRS 4 | A2C59514447 (with A2C59512084) |
| BMW | Z4 (E85/E86) | 06 - | ACSM | A2C59514447 |
| BMW | Z4 (E89) | 01/08 - | MRS 7 | A2C59514447 |
| BMW | Z8 (E52) | 00 - 03 | MRS 3, MRS 4 | A2C59514447 (with A2C59512084) |
| Citroen | Berlingo | 96 - 00 | Airbag/ Seat Belt | A2C59514447 (with A2C59512080) |
| Citroen | Berlingo | 00 - | Autoliv ACU /TRW Airbag | A2C59514447 |
| Citroen | C1 | 05 - | TRW Airbag | A2C59514447 |
| Citroen | C2 | 03 - | Autoliv ACU | A2C59514447 |
| Citroen | C2 | 03 - | SAC Temic CAN | A2C59514447 |
| Citroen | C3 | 02 - | Temic SRS | A2C59514447 |
| Citroen | C3 II | 05 - | SAC Temic CAN | A2C59514447 |
| Citroen | C4 | 04 - | Temic SRS | A2C59514447 |
| Citroen | C4 / C4 Picasso | 03 - | SAC Autoliv CAN | A2C59514447 |
| Citroen | C5 | 00 - | Temic SRS | A2C59514447 |
| Citroen | C5 II | 04 - | SAC Autoliv CAN | A2C59514447 |
| Citroen | C6 | 05 - | SAC Autoliv CAN | A2C59514447 |
| Citroen | C8 | 02 - | Temic SRS | A2C59514447 |
| Citroen | C8 | 06 - | SAC Temic CAN | A2C59514447 |
| Citroen | C Crosser | 07 - | SAC TRW CAN | A2C59514447 |
| Citroen | Dispatch/Jumpy | 95 - 00 | Airbag / Seat Belt / Side Airbags | A2C59514447 (with A2C59512080) |
| Citroen | Dispatch/Jumpy | 00 - | Autoliv ACU | A2C59514447 |
| Citroen | Evasion | 95 - 00 | Airbag / Seat Belt / Side Airbags | A2C59514447 (with A2C59512080) |
| Citroen | Evasion | 00 - | Autoliv ACU | A2C59514447 |
| Citroen | Relay / Jumper | 94 - 00 | Breed SRS / Breed 97 MY / Siemens 99 MY | Use Fiat Ducato |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|--------------------------|---------|--|--------------------------------|
| Citroen | Saxo | 96 - 00 | Airbag / Seat Belt | A2C59514447 (with A2C59512080) |
| Citroen | Saxo | 00 - 03 | Autoliv ACU | A2C59514447 |
| Citroen | Synergie | 96 - 00 | Airbag/ Seat Belt/ Side Airbags | A2C59514447 (with A2C59512080) |
| Citroen | Synergie | 00 - 03 | Autoliv ACU | A2C59514447 |
| Citroen | Xantia | 96 - 00 | Airbag/ Seat Belt/ Side Airbags | A2C59514447 (with A2C59512080) |
| Citroen | Xantia | 00 - 02 | Autoliv ACU | A2C59514447 |
| Citroen | XM | 96 - 98 | Airbag/ Seat Belt | A2C59514447 (with A2C59512080) |
| Citroen | XM | 00 - 01 | Autoliv ACU | A2C59514447 |
| Citroen | Xsara | 00 - | Autoliv ACU | A2C59514447 |
| Citroen | Xsara Picasso | 00 - | Autoliv ACU | A2C59514447 |
| Fiat | 500 | 07 - | SIEMENS Airbag (EP-Proxi) | A2C59514447 |
| Fiat | Barchetta | 96 - 98 | TRW2 Airbag w/pretensioners | A2C59514447 (with A2C5952975) |
| Fiat | Barchetta | 97 - 00 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Bravo/Brava | 95 - 00 | Breed | A2C59514447 (with A2C5952975) |
| Fiat | Bravo/Brava | 97 - 02 | Breed MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Bravo '07 | 07 - | TRW MY03 | A2C59514447 |
| Fiat | Coupe | 94 - 02 | TRW2 , TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Croma '05 | 05 - | TRW MY03 | A2C59514447 |
| Fiat | Doblo | 00 - 05 | Autoliv MY99 | A2C59514447 |
| Fiat | Ducato | 94 - 02 | Breed Airbag w/pretensioners, Breed MY97, TRW MY99 | A2C59514447 (with A2C5952975) |
| Fiat | Ducato RST | 01 - | Siemens MY99 | A2C59514447 |
| Fiat | Idea | 04 - | TRW MY03 | A2C59514447 |
| Fiat | Marea/Weekend | 96 - 02 | Allied Signal, Allied MY97, Breed MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Multipla | 98 - 01 | Breed 97 | A2C59514447 (with A2C5952975) |
| Fiat | Multipla | 02 - | Siemens MY99 | A2C59514447 |
| Fiat | Palio | 97 - 01 | TRW2, TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Palio RST | 01 - 02 | TRW MY97 | A2C59514447 |
| Fiat | Palio RST 2 | 02 - | TRW MY97 | A2C59514447 |
| Fiat | Panda '03 | 03 - | TRW MY99 | A2C59514447 |
| Fiat | Punto | 93 - 99 | TRW2, TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Punto '99 | 99 - 03 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Punto '03 | 03 - 05 | TRW MY97, TRW MY99 | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) | 05 - | TRW Airbag (EP-Proxi) | A2C59514447 |
| Fiat | Scudo | 96 - 04 | Autoliv ACU, Autoliv Central Airbags | A2C59514447 (with A2C59512080) |
| Fiat | Seicento | 98 - 04 | TRW MY97 | A2C59514447 (with A2C5952975) |
| Fiat | Stilo | 01 - 07 | Siemens MY99 | A2C59514447 |
| Fiat | Ulysse | 95 - 02 | Autoliv Central Airbags, Autoliv side airbags | A2C59514447 (with A2C59512080) |
| Fiat | Ulysse '02 | 02 - 05 | Temic SRS | A2C59514447 (with A2C59512080) |
| Ford | Cougar | 99 - 02 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | Crown Victoria | 96 - 98 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | Crown Victoria | 98 - 07 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Crown Victoria | 00 - 07 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Escort | 95 - 02 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Expedition | 97 - 99 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | Expedition | 99 - 08 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Explorer | 96 - 06 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | Explorer | 00 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Excursion | 00 - 05 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Excursion | 05 - | RCM - Restraint Control Module | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|------|--------------------------|---------|---------------------------------|------------------|
| Ford | E-Series | 97 - 05 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | E-Series | 05 - 08 | RCM - Restraint Control Module | A2C59514447 |
| Ford | F-250 Light Duty | 97 - 99 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | F-250 Light Duty | 99 - 02 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Fiesta | 99 - 07 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Fiesta | 02 - 07 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Fiesta | 08 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Focus I | 99 - 04 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Focus I | 99 - 04 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Focus II | 04 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Focus C-MAX | 02 - | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Focus C-MAX | 02 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | F-Series Super Duty | 99 - 02 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | F-Series Super Duty | 01 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Galaxy | 99 - 06 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Galaxy | 06 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | GT | 05 - 06 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Fusion | 02 - 08 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Fusion II | 09 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Ka | 96 - 08 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Ka II | 08 - | Airbag | A2C59514447 |
| Ford | Street Ka | 03 - 08 | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | Kuga | 08 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Maverick | 01 - 04 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Maverick 05 | 05 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Mondeo III | 01 - 06 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Mondeo IV | 07 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Ranger | 06 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | S-Max | 06 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Transit | 00 - 06 | RCM - Restraint Control Module | A2C59514447 |
| Ford | Transit | 06 - | RCM - Restraint Control Module | A2C59514447 |
| Ford | Transit / Torneo Connect | 02 - | ECS - Electronic Crash Sensor | A2C59514447 |
| Ford | WindStar | 96 - 98 | IABM - Integrated Airbag Module | A2C59514447 |
| Ford | WindStar | 99 - 04 | RCM - Restraint Control Module | A2C59514447 |
| GM | Agila-A | 00 - 08 | Agila SRS | A2C59514447 |
| GM | Astra F | 94 - 98 | Airbag S | A2C59514447 |
| GM | Astra-G | 98 - 04 | Airbag SAB6 | A2C59514447 |
| GM | Astra-H | 04 - | Astra-H SDM Airbag | A2C59514447 |
| GM | Calibra | 93 - 97 | Airbag S | A2C59514447 |
| GM | Cavalier | 93 - 95 | Airbag S | A2C59514447 |
| GM | Combo | 02 - 06 | Airbag 20 | A2C59514447 |
| GM | Corsa-B | 94 - 01 | Airbag S | A2C59514447 |
| GM | Corsa-B | 94 - 01 | Airbag SAB6 | A2C59514447 |
| GM | Corsa-C | 01 - 06 | Airbag 20 | A2C59514447 |
| GM | Corsa-D | 06 - | Corsa-D SDM Airbag | A2C59514447 |
| GM | Frontera-A | 97 - 98 | Airbag SDM (5V) | A2C59514447 |
| GM | Frontera-B | 99 - 02 | Airbag SDM (5V) | A2C59514447 |
| GM | Meriva-A | 03 - 08 | Airbag 20 | A2C59514447 |
| GM | Monterey | 97 - 98 | Airbag SDM (5V) | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|-------------------|---------|-----------------------|--------------------------------|
| GM | Movano | 04 - 06 | Airbag ACU3 (Renault) | A2C59514447 |
| GM | Omega-B | 94 - 99 | Airbag S | A2C59514447 |
| GM | Omega-B | 94 - 01 | Airbag SAB6 | A2C59514447 |
| GM | Omega-B | 01 - 03 | Airbag 20 | A2C59514447 |
| GM | Signum | 01 - | Signum SDM Airbag | A2C59514447 |
| GM | Speedster / VX220 | 01 - 06 | Airbag | A2C59514447 |
| GM | Tigra-A | 95 - 99 | Airbag S | A2C59514447 |
| GM | Tigra-B | 05 - 08 | Airbag 20 | A2C59514447 |
| GM | Vectra-A | 93 - 95 | Airbag S | A2C59514447 |
| GM | Vectra-B | 95 - 01 | Airbag SAB6 | A2C59514447 |
| GM | Vectra-B | 95 - 01 | Airbag SAE4 | A2C59514447 |
| GM | Vectra-B | 95 - 01 | Airbag | A2C59514447 |
| GM | Vectra-C | 01 - | Vectra-C SDM Airbag | A2C59514447 |
| GM | Vivaro | 01 - 06 | Airbag ACU3 (Renault) | A2C59514447 |
| GM | Zafira-A | 99 - 05 | Airbag SAB6 | A2C59514447 |
| GM | Zafira-B | 05 - | Zafira-B SDM Airbag | A2C59514447 |
| Honda | Accord V | 93 - 98 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | Accord VI | 98 - 03 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | Accord VII | 03 - 07 | SRS Type 03 | A2C59514447 |
| Honda | Civic VI | 95 - 01 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | Civic VII | 01 - 05 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | Civic VIII | 05 - | SRS Type 03 | A2C59514447 |
| Honda | CR-V I | 95 - 02 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | CR-V II | 02 - 06 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | CR-V III | 07 - | SRS Type 03 | A2C59514447 |
| Honda | FR-V | 04 - 09 | SRS Type 94/96/99 | A2C59514447 |
| Honda | Jazz I | 02 - 07 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | Prelude V | 96 - 00 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Honda | S2000 | 99 - 09 | SRS Type 94/96/99 | A2C59514447 (with A2C59514540) |
| Hyundai | Accent | 94 - 00 | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Accent II | 00 - | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Amica | 99 - | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Amica | 99 - | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Atos | 98 - | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Atos | 98 - | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Coupe | 96 - 02 | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Coupe | 96 - 02 | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Coupe II | 01 - | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Coupe II | 01 - | SRS C (KW2K) | A2C59514447 |
| Hyundai | Elantra III | 00 - 06 | SRS FISO | A2C59514447 |
| Hyundai | Getz | 02 - | SRS G (KW2K) | A2C59514447 |
| Hyundai | Getz | 02 - | SRS G TBEP (KW2K) | A2C59514447 |
| Hyundai | Lantra II | 95 - 00 | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Matrix | 01 - 05 | SRS FISO | A2C59514447 |
| Hyundai | Santa Fé | 01 - 07 | SRS 97/99 (Carb) | A2C59514447 |
| Hyundai | Santa Fé | 01 - 07 | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Sonata IV | 01 - 04 | SRS T (KW2K) | A2C59514447 |
| Hyundai | Terrecan | 01 - 07 | SRS 00 (Carb) | A2C59514447 |
| Hyundai | Trajet | 00 - 08 | SRS 00 (Carb) | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|------------|--------------------------|------------|---------------------------------------|--------------------------------|
| Hyundai | Tuscon | 04 - 09 | SRS T (KW2K) | A2C59514447 |
| Jaguar | S-Type | 99 - 08 | SRS F-9141 | A2C59514447 |
| Jaguar | X-Type | 01 - 08 | SRS F-9141 | A2C59514447 |
| Jaguar | XJ/XJR (X350) | 03 - 09 | SRS F-9141 | A2C59514447 |
| Jaguar | XK/XKR (X100) | 96 - 06 | SRS P3 F-9141 | A2C59514447 |
| Jaguar | XK/XKR (X150) | 06 - | SRS CAN XK | A2C59514447 |
| Lancia | Kappa | 94 - 01 | TRW2 Airbag w/pretensioners, TRW MY97 | A2C59514447 (with A2C5952975) |
| Lancia | Lybra | 99 - 06 | Allied MY97, Siemens MY99 | A2C59514447 (with A2C5952975) |
| Lancia | Musa | 04 - 06 | TRW MY03 | A2C59514447 |
| Lancia | Phedra | 02 - 06 | Temic SRS | A2C59514447 (with A2C59512080) |
| Lancia | Thesis | 02 - 06 | TRW MY99 | A2C59514447 |
| Lancia | Y | 96 - 03 | Allied Signal, Allied MY97 | A2C59514447 (with A2C5952975) |
| Lancia | Ypsilon | 03 - 06 | Autoliv MY99 | A2C59514447 |
| Lancia | Z | 96 - 02 | Autoliv, Autoliv ACU | A2C59514447 (with A2C59512080) |
| Land Rover | Freelander | 98 - 02 | Autoliv AC4 | A2C59514447 |
| Land Rover | Freelander | 03 - 06 | Siemens SRE Smart | A2C59514447 |
| Land Rover | Freelander II (L359) | 07 - | RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Discovery | 96 - 98 | TRW SPS | A2C59514447 |
| Land Rover | Discovery II | 98 - 04 | TRW Generation 4 | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Discovery IV (L319) | 10 | MY10 RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Range Rover (P38a) | 97 - 02 | TRW SPS | A2C59514447 |
| Land Rover | Range Rover (L322) | 03 - 06 | Bosch MRS4 | A2C59514447 |
| Land Rover | Range Rover (L322) | 07 - 09 | RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Range Rover (L322) | 10 | MY10 RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | RCM - Restraint Control Module | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 10 | MY10 RCM - Restraint Control Module | A2C59514447 |
| Lexus | GS II | 97 - 04 | SRS KW2 9600 | A2C59514447 |
| Lexus | GS III | 05 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Lexus | IS | 98 - 05 | SRS KW2 9600 | A2C59514447 |
| Lexus | IS II | 06 - | SRS KW2 10400 | A2C59514447 |
| Lexus | LS III | 01 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Lexus | LS IV | 06 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Lexus | RX | 98 - 03 | SRS KW2 9600 | A2C59514447 |
| Lexus | RX II | 04 - 09 | SRS KW2 9600 | A2C59514447 |
| Lexus | SC II | 01 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Mazda | 2 | 03 - 07 | SRS F-9141 | A2C59514447 |
| Mazda | 3 | 04 - 08 | SRS CAN | A2C59514447 |
| Mazda | 5 | 05 - 08 | SRS F-9141 | A2C59514447 |
| Mazda | 6 | 02 - 08 | SRS F-9141 | A2C59514447 |
| Mazda | MX-5 III | 05 - 08 | SRS F-9141 | A2C59514447 |
| Mazda | RX-8 | 03 - | SRS F-9141 | A2C59514447 |
| Mercedes | A Class (W168) | 98 - 03 | Fast Codes | A2C59514447 |
| Mercedes | A Class (W169) | 04 - | AB 169 | A2C59514447 |
| Mercedes | B Class (W245) | 05 - | AB 169 | A2C59514447 |
| Mercedes | C Class (W202) | 93 - 01 | Fast Codes | A2C59514447 |
| Mercedes | C Class (W203) | 00 - 09/03 | Arminca | A2C59514447 |
| Mercedes | C Class (W203) | 09/03 - 07 | Armada | A2C59514447 |
| Mercedes | C Class (W203) | 09/03 - 07 | WSS | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|----------|--------------------------------------|------------|------------|--------------------------------|
| Mercedes | CL Class (W215) | 99 - 09/02 | Armin | A2C59514447 |
| Mercedes | CL Class (W215) | 09/02 - 06 | Armada 2 | A2C59514447 |
| Mercedes | CLK (W208) | 93 - 03 | Fast Codes | A2C59514447 |
| Mercedes | CLK (W209) | 02 - 04/04 | Arminca | A2C59514447 |
| Mercedes | CLK (W209) | 04/04 - 02 | Armada | A2C59514447 |
| Mercedes | CLK (W209) | 04/04 - 02 | WSS | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | Armada | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | RGSL 211 | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | RGRS 211 | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | WSS | A2C59514447 |
| Mercedes | E Class (W210) | 95 - 03 | Fast Codes | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | Armada | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | RGSL 211 | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | RGRS 211 | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | WSS | A2C59514447 |
| Mercedes | G Class (W461) | 98 - 02 | Fast Codes | A2C59514447 |
| Mercedes | G Class (W463) | 98 - | Fast Codes | A2C59514447 |
| Mercedes | G Class (W463) | 98 - | Armin | A2C59514447 |
| Mercedes | M Class (W163) | 93 - 03 | Fast Codes | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | Arcade 164 | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | RGSL 164 | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | RGRS 164 | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | WSS | A2C59514447 |
| Mercedes | R Class (251) | 05 - | Arcade 164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | RGSL 164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | RGRS 164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | WSS | A2C59514447 |
| Mercedes | S Class (W140) | 91 - 08 | Fast Codes | A2C59514447 |
| Mercedes | S Class (W220) | 98 - 09/02 | Fast Codes | A2C59514447 |
| Mercedes | S Class (W220) | 09/02 - | Armada 2 | A2C59514447 |
| Mercedes | S Class (W220) | 09/02 - | REVASL | A2C59514447 |
| Mercedes | S Class (W220) | 09/02 - | REVASR | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | Arcade 221 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | RGSL 221 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | RGRS 221 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | WSS 221 | A2C59514447 |
| Mercedes | SL (R129) | 93 - 03 | Fast Codes | A2C59514447 |
| Mercedes | SL (R230) | 03 - 06 | Armada 2 | A2C59514447 |
| Mercedes | SLK (R170) | 93 - 03 | Fast Codes | A2C59514447 |
| Mercedes | SLK (R171) | 04 - | Armada | A2C59514447 |
| Mercedes | SLR (199) | 04 - | Armada 2 | A2C59514447 |
| Mercedes | Sprinter (W901 / W902 / W903 / W904) | 95 - 02 | Fast Codes | A2C59514447 (with A2C59512082) |
| Mercedes | Vaneo (414) | 02 - | Armin | A2C59514447 |
| Mercedes | Viano (639) | 03 - | Armada | A2C59514447 |
| Mercedes | Vito (639) | 03 - | Armada | A2C59514447 |
| MINI | MINI (R50 / R53) | 00 - 07 | MRS 4 | A2C59514447 |
| MINI | MINI (R55 / R56 / R57 / R60) | 06 - | MRS 6 | A2C59514447 |
| Nissan | 350Z | 03 - 09 | SRS-A | A2C59514447 |
| Nissan | Almera II | 02 - 07 | SRS-A | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|-------------------|---------|---|--------------------------------|
| Nissan | Almera Tino (V10) | 00 - 06 | SRS-A | A2C59514447 |
| Nissan | Micra (K11) | 92 - 02 | SRS-A | A2C59514447 |
| Nissan | Micra (K12) | 03 - 07 | SRS-A | A2C59514447 |
| Nissan | Micra C+C | 05 - 07 | SRS-A | A2C59514447 |
| Nissan | Navara | 04 - | SRS-A | A2C59514447 |
| Nissan | Note | 06 - | SRS-A | A2C59514447 |
| Nissan | Primera (P12) | 02 - 08 | SRS-A | A2C59514447 |
| Nissan | Qashqai | 07 - | SRS-A | A2C59514447 |
| Nissan | X-Trail | 01 - 07 | SRS-A | A2C59514447 |
| Peugeot | 107 | 05 - | TRW Airbag | A2C59514447 |
| Peugeot | 1007 | 04 - 06 | TRW Airbag | A2C59514447 |
| Peugeot | 1007 | 04 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 106 | 96 - 00 | Airbag / Seat Belt | A2C59514447 (with A2C59512080) |
| Peugeot | 106 | 00 - 04 | Autoliv ACU | A2C59514447 |
| Peugeot | 206 | 98 - 00 | Airbag / Seat Belt / Side Airbags | A2C59514447 (with A2C59512080) |
| Peugeot | 206 | 00 - 06 | Autoliv ACU / Temic SRS | A2C59514447 |
| Peugeot | 207 | 06 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 306 | 96 - 00 | Airbag / Seat Belt / Side Airbags | A2C59514447 (with A2C59512080) |
| Peugeot | 306 | 00 - 02 | Autoliv ACU | A2C59514447 |
| Peugeot | 307 | 01 - 07 | Temic SRS | A2C59514447 |
| Peugeot | 307 II | 04 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 308 | 07 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 406 | 95 - 00 | Airbag/ Seat Belt/ Side Airbags | A2C59514447 (with A2C59512080) |
| Peugeot | 406 | 00 - 03 | Autoliv ACU | A2C59514447 |
| Peugeot | 407 | 05 - | Temic SRS | A2C59514447 |
| Peugeot | 407 | 05 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 605 | 97 - 00 | Airbag/ Seat Belt/ Side Airbags | A2C59514447 (with A2C59512080) |
| Peugeot | 607 | 01 - 06 | Temic SRS | A2C59514447 |
| Peugeot | 806 | 96 - 00 | Airbag/ Seat Belt/ Side Airbags | A2C59514447 (with A2C59512080) |
| Peugeot | 806 | 00 - 03 | Autoliv ACU | A2C59514447 |
| Peugeot | 807 | 02 - | Temic SRS | A2C59514447 |
| Peugeot | 807 | 05 - | SAC Gonflable CAN | A2C59514447 |
| Peugeot | 4007 | 07 - | SAC TRW CAN | A2C59514447 |
| Peugeot | Boxer | 96 - 00 | Breed SRS / Breed 97 MY / Siemens 99 MY | A2C59514447 (with A2C59512080) |
| Peugeot | Expert | 97 - 00 | Airbag/ Seat Belt | A2C59514447 |
| Peugeot | Expert | 00 - | Autoliv ACU | A2C59514447 (with A2C59512080) |
| Peugeot | Partner/Ranch | 96 - 00 | Airbag/ Seat Belt | A2C59514447 |
| Peugeot | Partner/Ranch | 00 - | Autoliv ACU / TRW Airbag | A2C59514447 |
| Renault | Avantime | 01 - 03 | Siemens Autoliv ACU3 | A2C59514447 |
| Renault | Clio II | 98 - 06 | AB7 | A2C59514447 |
| Renault | Clio II | 98 - 06 | AB8 | A2C59514447 |
| Renault | Clio III | 06 - | AB9 | A2C59514447 |
| Renault | Clio III | 06 - | Airbag | A2C59514447 |
| Renault | Espace IV | 02 - | Siemens Autoliv ACU3 | A2C59514447 |
| Renault | Espace IV | 02 - | Siemens Autoliv ACU4 | A2C59514447 |
| Renault | Kangoo | 97 - 02 | Siemens Autoliv ACU 3.8 | A2C59514447 |
| Renault | Kangoo | 97 - 02 | AC4 | A2C59514447 |
| Renault | Kangoo | 97 - 02 | AC4 Phase 2 | A2C59514447 |
| Renault | Kangoo | 97 - 02 | AC6 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|------------|---------|--------------------------|------------------|
| Renault | Kangoo | 97 - 02 | AC6 Phase 2 | A2C59514447 |
| Renault | Kangoo | 97 - 02 | EC5 | A2C59514447 |
| Renault | Kangoo II | 02 - 08 | Siemens Autoliv ACU 3.8 | A2C59514447 |
| Renault | Kangoo II | 02 - 08 | AC4 | A2C59514447 |
| Renault | Kangoo II | 02 - 08 | AC4 Phase 2 | A2C59514447 |
| Renault | Kangoo II | 02 - 08 | AC6 | A2C59514447 |
| Renault | Kangoo II | 02 - 08 | AC6 Phase 2 | A2C59514447 |
| Renault | Kangoo III | 08 - | AB9 | A2C59514447 |
| Renault | Laguna | 93 - 00 | AC4 | A2C59514447 |
| Renault | Laguna | 93 - 00 | AC4 Phase 2 | A2C59514447 |
| Renault | Laguna | 93 - 00 | AC6 | A2C59514447 |
| Renault | Laguna | 93 - 00 | AC6 Phase 2 | A2C59514447 |
| Renault | Laguna | 93 - 00 | EC5 | A2C59514447 |
| Renault | Laguna II | 01 - 07 | Siemens Autoliv ACU3 | A2C59514447 |
| Renault | Laguna II | 01 - 07 | Siemens Autoliv ACU3.8 | A2C59514447 |
| Renault | Laguna II | 01 - 07 | Siemens Autoliv ACU4 | A2C59514447 |
| Renault | Laguna III | 08 - | Airbag 001D-04 | A2C59514447 |
| Renault | Master | 95 - | AC4 | A2C59514447 |
| Renault | Master | 95 - | AC4 Phase 2 | A2C59514447 |
| Renault | Master | 95 - | AC6 | A2C59514447 |
| Renault | Master | 95 - | AC6 Phase 2 | A2C59514447 |
| Renault | Master | 95 - | EC5 | A2C59514447 |
| Renault | Megane | 95 - 02 | AC4 | A2C59514447 |
| Renault | Megane | 95 - 02 | AC4 Phase 2 | A2C59514447 |
| Renault | Megane | 95 - 02 | AC6 | A2C59514447 |
| Renault | Megane | 95 - 02 | AC6 Phase 2 | A2C59514447 |
| Renault | Megane | 95 - 02 | ACU 3.8 | A2C59514447 |
| Renault | Megane | 95 - 02 | EC5 | A2C59514447 |
| Renault | Megane II | 02 - | Siemens Autoliv ACU4 MK2 | A2C59514447 |
| Renault | Megane II | 02 - | Siemens Autoliv ACU4 | A2C59514447 |
| Renault | Megane II | 02 - | Airbag 0021-14 | A2C59514447 |
| Renault | Modus | 04 - | AB9 | A2C59514447 |
| Renault | Modus | 04 - | Airbag | A2C59514447 |
| Renault | Scenic | 95 - 02 | AC4 | A2C59514447 |
| Renault | Scenic | 95 - 02 | AC4 Phase 2 | A2C59514447 |
| Renault | Scenic | 95 - 02 | AC6 | A2C59514447 |
| Renault | Scenic | 95 - 02 | AC6 Phase 2 | A2C59514447 |
| Renault | Scenic | 95 - 02 | EC5 | A2C59514447 |
| Renault | Scenic II | 03 - | Siemens Autoliv ACU4 MK2 | A2C59514447 |
| Renault | Scenic II | 03 - | Siemens Autoliv ACU3.8 | A2C59514447 |
| Renault | Scenic II | 03 - | Siemens Autoliv ACU4 | A2C59514447 |
| Renault | Trafic | 97 - 00 | AC4 | A2C59514447 |
| Renault | Trafic | 97 - 00 | AC4 Phase 2 | A2C59514447 |
| Renault | Trafic | 97 - 00 | EC5 | A2C59514447 |
| Renault | Trafic II | 01 - | Siemens Autoliv ACU3 | A2C59514447 |
| Renault | Twingo | 92 - 07 | AC4 | A2C59514447 |
| Renault | Twingo | 92 - 07 | AC4 Phase 2 | A2C59514447 |
| Renault | Twingo | 92 - 07 | AC6 | A2C59514447 |
| Renault | Twingo | 92 - 07 | AC6 Phase 2 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|---------|---------------------|---------|------------------------------|------------------|
| Renault | Twingo | 92 - 07 | EC5 | A2C59514447 |
| Renault | Twingo II | 07 - | Airbag 0401-04 | A2C59514447 |
| Renault | Vel Satis | 01 - | Siemens Autoliv ACU3 | A2C59514447 |
| Seat | Alhambra | 96 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Altea | 04 - | CAN | A2C59514447 |
| Seat | Arosa | 97 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Cordoba | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Ibiza | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 00 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 04 - | CAN | A2C59514447 |
| Seat | Toledo | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Toledo III | 04 - | CAN | A2C59514447 |
| Skoda | Fabia | 00 - 07 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Fabia II | 07 - | CAN | A2C59514447 |
| Skoda | Felicia | 95 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Octavia | 96 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Octavia II | 04 - | CAN | A2C59514447 |
| Skoda | Roomster | 06 - | CAN | A2C59514447 |
| Skoda | Superb | 02 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Yeti | 10 - | CAN | A2C59514447 |
| Toyota | Auris | 07 - | SRS KW2 10400 | A2C59514447 |
| Toyota | Avensis | 98 - 03 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Avensis II | 03 - 08 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Avensis Verso | 01 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Aygo | 05 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Camry (XV20) | 96 - 01 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Camry (XV30) | 01 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Celica VII | 99 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Corolla VIII (E110) | 97 - 02 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Corolla IX (E120) | 02 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Corolla Verso | 04 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Hiace IV | 98 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Hilux | 97 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Land Cruiser (J90) | 96 - 98 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Land Cruiser (J100) | 98 - 03 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Land Cruiser (J120) | 03 - | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | MR2 III (ZZW30) | 00 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Picnic I | 96 - 02 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Previa I | 97 - 00 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Previa II | 00 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Prius (NHW20) | 04 - 09 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | RAV4 I (XA1) | 97 - 00 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | RAV4 II (CA20W) | 00 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | RAV4 III (CA30W) | 06 - | SRS KW2 10400 | A2C59514447 |
| Toyota | Yaris I | 99 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Toyota | Yaris II | 06 - | SRS KW2 10400 | A2C59514447 |
| Toyota | Yaris Verso | 99 - 06 | SRS KW2 9600 / SRS KW2 10400 | A2C59514447 |
| Volvo | S40 | 04 - 06 | P1X | A2C59514447 |
| Volvo | V50 | 03 - 08 | P1X | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK AIRBAG

| Make | Model | From/To | System | Harness Required |
|-------|--------------------------|---------|------------------|--------------------------------|
| Volvo | S60 | 01 - 05 | P2X | A2C59514447 |
| Volvo | V70 | 00 - 07 | P2X | A2C59514447 |
| Volvo | XC70 | 00 - 06 | P2X | A2C59514447 |
| Volvo | S80 | 99 - 06 | P2X | A2C59514447 |
| Volvo | XC90 | 02 - 06 | P2X | A2C59514447 |
| VW | Amorak | 10 - | CAN | A2C59514447 |
| VW | Beetle | 99 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Bora | 98 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Bora | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Cabrio | 95 - 02 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Caddy | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Corrado | 91 - 95 | KWP1281 / KW2000 | A2C59514447 |
| VW | EOS | 05 - | CAN | A2C59514447 |
| VW | Eurovan | 99 - 03 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Golf/GTI | 91 - 03 | KWP1281 / KW2000 | A2C59514447 |
| VW | Golf/GTI | 03 - | CAN | A2C59514447 |
| VW | Golf Plus | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Jetta | 93 - 04 | KWP1281 / KW2000 | A2C59514447 |
| VW | Jetta | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Lupo | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 94 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Passat | 05 - | CAN | A2C59514447 |
| VW | Phaeton | 03 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Polo | 98 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Scirocco III | 09 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Sharan | 95 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 03 - 06 | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 07 - | CAN | A2C59514447 |
| VW | Touran | 03 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Transporter/Caravelle | 92 - 04 | KWP1281 / KW2000 | A2C59514447 |
| VW | Transporter/Caravelle T5 | 04 - | CAN | A2C59514447 |
| VW | Vento | 92 - 98 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|------------|----------------------------|------------|---|--------------------------------|
| Alfa Romeo | 145 | 94 - 00 | Borletti MCC55F Climate Control | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 146 | 95 - 00 | Borletti MCC55F Climate Control | A2C59514447 (with A2C59512975) |
| Alfa Romeo | 147 | 00 - 07 | Delphi (Single Zone) Delphi (Dual Zone) | A2C59514447 |
| Alfa Romeo | 156 | 97 - 02 | Harrison Climate Control | A2C59514447 |
| Alfa Romeo | 156 '02 | 02 - 05 | Delphi Climate Control | A2C59514447 |
| Alfa Romeo | 156 '02 | 02 - 05 | Delphi Climate Control MY 03 (Single zone) | A2C59514447 |
| Alfa Romeo | 159 | 05 - | Delphi (Single Zone) Delphi (Dual Zone) | A2C59514447 |
| Alfa Romeo | 166 | 98 - 07 | Borletti Climate Control MCC80X | A2C59514447 |
| Alfa Romeo | Brera | 05 - | Delphi (Single Zone) Delphi (Dual Zone) | A2C59514447 |
| Alfa Romeo | GT | 04 - | Delphi (Single Zone) Delphi (Dual Zone) | A2C59514447 |
| Alfa Romeo | GTV | 98 - 03 | Harrison Climate Control | A2C59514447 |
| Alfa Romeo | MiTo | 08 - | DENSO Single-zone climate control (EP) | A2C59514447 |
| Alfa Romeo | MiTo | 08 - | DENSO HEATER EP | A2C59514447 |
| Alfa Romeo | Spider | 98 - 03 | Harrison Climate Control | A2C59514447 |
| Alfa Romeo | Spider (939) | 07 - | Delphi (Single Zone) Delphi (Dual Zone) | A2C59514447 |
| Audi | 80/Cabrio/Coupe/Quattro | 94 - 96 | KWP1281 | A2C59514447 (with A2C59512079) |
| Audi | A2 | 01 - 06 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 96 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 04 - | CAN | A2C59514447 |
| Audi | A4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A4 | 04 - | CAN | A2C59514447 |
| Audi | S4 | 92 - 02 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| Audi | S4 | 04 - | CAN | A2C59514447 |
| Audi | A5 | 08 - | CAN | A2C59514447 |
| Audi | S5 | 08 - | CAN | A2C59514447 |
| Audi | A6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A6 | 04 - | CAN | A2C59514447 |
| Audi | S6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S6 | 04 - | CAN | A2C59514447 |
| Audi | Allroad Quattro | 01 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | Q5 | 09 - | CAN | A2C59514447 |
| Audi | Q7 | 06 - | CAN | A2C59514447 |
| Audi | A8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A8 | 04 - | CAN | A2C59514447 |
| Audi | R8 | 07 - | CAN | A2C59514447 |
| Audi | S8 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S8 | 04 - | CAN | A2C59514447 |
| Audi | TT | 98 - 07 | KWP1281/KW2000 | A2C59514447 |
| Audi | TT | 07 - | CAN | A2C59514447 |
| Audi | 100 | 94 - 97 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| BMW | 1 Series (E81/E87) | 04 - 03/07 | IHR E87 / E90, IHKR E87 / E90, IHKA E87 / E90 | A2C59514447 |
| BMW | 1 Series (E81/E82/E87/E88) | 03/07 - | IHR E87 / E90 (CAN), IHKR E87 / E90 (CAN), IHKA E87 / E90 (CAN) | A2C59514447 |
| BMW | 1 Series (F20) | 07/10 - | IHKA | A2C59514447 |
| BMW | 3 Series (E36) | 90 - 98 | IHKA E36 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E46) | 98 - 05 | IHKR E46 / E83, IHKA E46 / E83 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E90/E91/E92/E93) | 05 - 03/07 | IHR E87 / E90, IHKR E87 / E90, IHKA E87 / E90 | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | IHR E87 / E90 (CAN), IHKR E87 / E90 (CAN), IHKA E87 / E90 (CAN) | A2C59514447 |
| BMW | 5 Series (E39) | 96 - 04 | IHR E39, IHKR E39 / E53, IHKA E39 / E53, IHKA E39 | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E60/E61) | 04 - 03/07 | IHKA E60 / E63 / E65 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|---------|--------------------------|------------|---|--------------------------------|
| BMW | 5 Series (E60/E61) | 03/07 - | IHKA E60 / E63 / E65 (CAN), IHKA 2 E60 / E63 | A2C59514447 |
| BMW | 5 Series (F07/F10/F11) | 01/09 - | IHKA | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 03/07 | IHKA E60 / E63 / E65 | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | IHKA E60 / E63 / E65 (CAN), IHKA 2 E60 / E63 | A2C59514447 |
| BMW | 6 Series (F12) | 10/09 - | IHKA | A2C59514447 |
| BMW | 7 Series (E38) | 94 - 02 | IHKR E38, IHKA E38, FGB E38, FHK E38 | A2C59514447 (with A2C59512084) |
| BMW | 7 Series (E65) | 02 - 03/07 | IHKA E60/E63/E65 | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | IHKA E60 / E63 / E65 (CAN) | A2C59514447 |
| BMW | 7 Series (F01/F02/F04) | 06/07 - | IHKA | A2C59514447 |
| BMW | X1 (E84) | 09/08 - | IHKA | A2C59514447 |
| BMW | X3 (E83) | 03 - | IHKR E46 / E83, IHKA E46 / E83 | A2C59514447 |
| BMW | X3 (F25) | 06/09 - | IHKA | A2C59514447 |
| BMW | X5 (E53) | 00 - | IHKR E39 / E53, IHKA E39 / E53 | A2C59514447 |
| BMW | X5 (E70) | 06 - | IHKA E87/E90 (CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | IHKA E87/E90 (CAN) | A2C59514447 |
| BMW | Z3 (E36) | 96 - 03 | IHKA E36 | A2C59514447 (with A2C59512084) |
| BMW | Z4 (E85) | 03 - | IHS/IHKS E85, IHKA E85 | A2C59514447 |
| BMW | Z4 (E89) | 01/08 - | IHKA | A2C59514447 |
| BMW | Z8 (E52) | 00 - 03 | IHKS E52 | A2C59514447 (with A2C59512084) |
| Citroen | C2 | 03 - | Valeo CAN | A2C59514447 |
| Citroen | C3 | 00 - | Behr | A2C59514447 |
| Citroen | C3 II | 05 - | Valeo CAN | A2C59514447 |
| Citroen | C4 /C4 Picasso | 03 - | Clim B5 CAN | A2C59514447 |
| Citroen | C5 | 99 - | Valeo | A2C59514447 |
| Citroen | C6 | 05 - | Bi-Zone Z9 CAN | A2C59514447 |
| Citroen | C8 | 02 - 06 | Regulee V | A2C59514447 |
| Citroen | C8 | 06 - | Mono-Zone V CAN | A2C59514447 |
| Citroen | C Crosser | 07 - | Clim Mitsubishi CAN | A2C59514447 |
| Citroen | Xantia | 99 - | Valeo | A2C59514447 |
| Citroen | Xsara | 00 - | Behr | A2C59514447 |
| Fiat | 500 | 07 - | DENSO Single-zone climate control (EP) | A2C59514447 |
| Fiat | 500 | 07 - | DENSO_HEATER_EP | A2C59514447 |
| Fiat | Bravo/Brava | 95 - 02 | Borletti MCC55F Climate Control | A2C59514447 (with A2C59512975) |
| Fiat | Coupe | 96 - 02 | Borletti MCC55F Climate Control | A2C59514447 (with A2C59512975) |
| Fiat | Croma '05 | 05 - | Valeo Climate Control (Two Zone) | A2C59514447 |
| Fiat | Idea | 04 - | Denso Climate Control 1 (Two Zone) | A2C59514447 |
| Fiat | Marea/Weekend | 96 - 02 | Borletti MCC55F Climate Control | A2C59514447 (with A2C59512975) |
| Fiat | Multipla | 98 - | Borletti MCC55F Climate Control | A2C59514447 |
| Fiat | Panda '03 | 03 - 05 | Denso Climate Control 1 (Single Zone) | A2C59514447 |
| Fiat | Punto '03 | 03 - 05 | Denso 2 Climate Control (Two Zone) | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) | 05 - | Denso Climate Control (EP) | A2C59514447 |
| Fiat | Stilo | 01 - 07 | Marelli Climate Control | A2C59514447 |
| Fiat | Ulysse | 95 - 02 | Behr Climate Control | A2C59514447 |
| Ford | Crown Victoria | 95 - 07 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Expedition | 99 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Expedition | 99 - | RCC - Remote Climate Control | A2C59514447 |
| Ford | Explorer | 94 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Fiesta | 02 - 07 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Fiesta | 08 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|------------|----------------------|---------|---|--------------------------------|
| Ford | Focus I | 98 - 03 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Focus II | 04 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Focus C-MAX | 02 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Fusion | 02 - 08 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Fusion II | 09 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Galaxy | 99 - 06 | RCC - Remote Climate Control | A2C59514447 |
| Ford | Galaxy | 06 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Ka | 00 - 08 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Ka II | 08 - | Climate Control | A2C59514447 |
| Ford | Kuga | 08 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Mondeo | 00 - 06 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Mondeo IV | 07 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | S-Max | 06 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Transit | 00 - 06 | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| Ford | Transit | 06 - | EATC - Electronic Automatic Temperature Control | A2C59514447 |
| GM | Astra-G | 02 - 04 | | A2C59514447 |
| GM | Astra-H | 04 - | ECC/SAC | A2C59514447 |
| GM | Corsa-C | 03 - 06 | | A2C59514447 |
| GM | Corsa-D | 06 - | ECC/SAC | A2C59514447 |
| GM | Corsa-D | 06 - | HVA | A2C59514447 |
| GM | Meriva-A | 03 - 08 | | A2C59514447 |
| GM | Omega-B | 94 - 99 | | A2C59514447 |
| GM | Omega-B | 00 - 03 | | A2C59514447 |
| GM | Signum | 01 - | ECC/SAC | A2C59514447 |
| GM | Signum | 01 - | HVA | A2C59514447 |
| GM | Vectra-B | 95 - 01 | | A2C59514447 |
| GM | Vectra-C | 01 - | ECC/SAC | A2C59514447 |
| GM | Vectra-C | 01 - | HVA | A2C59514447 |
| GM | Zafira-A | 03 - 05 | | A2C59514447 |
| GM | Zafira-B | 05 - | ECC/SAC | A2C59514447 |
| Honda | Accord VII | 03 - 07 | HVAC | A2C59514447 |
| Honda | Civic VIII | 05 - | HVAC | A2C59514447 (with A2C59514540) |
| Honda | CR-V II | 02 - 06 | HVAC | A2C59514447 (with A2C59514540) |
| Hyundai | Sonata IV | 01 - 04 | A/C FATC (KW2K) | A2C59514447 |
| Hyundai | Tuscon | 04 - 09 | A/C FATC (KW2K) | A2C59514447 |
| Jaguar | S-Type | 99 - 08 | AC SCP, AC-CC CAN | A2C59514447 |
| Jaguar | X-Type | 01 - 08 | AC SCP, AC-CC CAN | A2C59514447 |
| Jaguar | XK/XKR (X100) | 96 - 06 | AC F-9141 | A2C59514447 |
| Lancia | Lybra | 99 - 06 | Marelli / Hella Climate Control | A2C59514447 |
| Lancia | Musa | 04 - 06 | Denso 1 Climate Control (Two Zone) | A2C59514447 |
| Lancia | Thesis | 02 - 06 | Borletti / Hella Climate Control | A2C59514447 |
| Lancia | Ypsilon | 03 - 06 | Denso Climate Control (Two Zone) | A2C59514447 |
| Lancia | Z | 96 - 02 | Behr Climate Control | A2C59514447 |
| Land Rover | Freelander II (L359) | 07 - | Hevac | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | HVAC | A2C59514447 |
| Land Rover | Discovery IV (L319) | 10 | MY10 HVAC | A2C59514447 |
| Land Rover | Range Rover (P38a) | 97 - 02 | Hevac | A2C59514447 |
| Land Rover | Range Rover (L322) | 03 - 06 | Hevac | A2C59514447 |
| Land Rover | Range Rover (L322) | 07 -09 | HVAC | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|------------|--------------------------|------------|--------------|--------------------------------|
| Land Rover | Range Rover (L322) | 10 | MY10 HVAC | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | HVAC | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 10 | MY10 HVAC | A2C59514447 |
| Lexus | GS II | 97 - 04 | AC KW2 9600 | A2C59514447 |
| Lexus | GS III | 05 - | AC KW2 9600 | A2C59514447 |
| Lexus | IS | 98 - 05 | AC KW2 9600 | A2C59514447 |
| Lexus | IS II | 06 - | AC KW2 9600 | A2C59514447 |
| Lexus | LS III | 01 - 06 | AC KW2 9600 | A2C59514447 |
| Lexus | LS IV | 06 - | AC KW2 9600 | A2C59514447 |
| Lexus | RX | 98 - 03 | AC KW2 9600 | A2C59514447 |
| Lexus | RX II | 04 - 09 | AC KW2 9600 | A2C59514447 |
| Lexus | SC II | 01 - | AC KW2 9600 | A2C59514447 |
| Mazda | 5 | 05 - 08 | AC CAN | A2C59514447 |
| Mercedes | A Class (W168) | 98 - 03 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | A Class (W169) | 04 - | KLA 169 | A2C59514447 |
| Mercedes | B Class (W245) | 05 - | KLA 169 | A2C59514447 |
| Mercedes | C Class (W202) | 93 - 01 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | C Class (W203) | 00 - 09/03 | KLA203 | A2C59514447 (with A2C59512083) |
| Mercedes | C Class (W203) | 09/03 - 07 | KLA203 (CAN) | A2C59514447 |
| Mercedes | C Class (W203) | 09/03 - 07 | STH 211 | A2C59514447 |
| Mercedes | CL Class (W215) | 99 - 06 | KLA220 | A2C59514447 (with A2C59512083) |
| Mercedes | CL Class (W215) | 09/02 - 06 | STH 220 | A2C59514447 |
| Mercedes | CLK (W208) | 98 - 02 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | CLK (W209) | 02 - | KLA203 | A2C59514447 (with A2C59512083) |
| Mercedes | CLK (W209) | 04/04 - 02 | KLA203 (CAN) | A2C59514447 |
| Mercedes | CLK (W209) | 04/04 - 02 | STH 211 | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | KLA 211 | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | STH 211 | A2C59514447 |
| Mercedes | E Class (W210) | 95 - 03 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | E Class (W211) | 02 - | KLA 211 | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | LRK 211 | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | STH 211 | A2C59514447 |
| Mercedes | G Class (W461) | 98 - 02 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | G Class (W463) | 98 - 04/04 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | G Class (W463) | 04/04 - | KLA203 (CAN) | A2C59514447 |
| Mercedes | G Class (W463) | 04/04 - | STH 203 | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | KLA 164 | A2C59514447 |
| Mercedes | M Class (W164) | 05 - | STH 164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | KLA 164 | A2C59514447 |
| Mercedes | R Class (251) | 05 - | STH 164 | A2C59514447 |
| Mercedes | S Class (W140) | 95 - 03 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | S Class (W220) | 99 - 03 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | S Class (W220) | 09/02 - | STH 220 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | KLA 221 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | HVCR 221 | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | STH 221 | A2C59514447 |
| Mercedes | SL Class (R129) | 95 - 03 | KLA | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | KLA230 | A2C59514447 (with A2C59512083) |
| Mercedes | SLK (R170) | 98 - 03 | KLA | A2C59514447 (with A2C59512083) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|----------|--------------------------------------|---------|--------------------------------------|--------------------------------|
| Mercedes | SLK (R171) | 04 - | KLA 171 | A2C59514447 |
| Mercedes | SLR (199) | 04 - | SLA230 | A2C59514447 (with A2C59512083) |
| Mercedes | Sprinter (W901 / W902 / W903 / W904) | 95 - 02 | KLA | A2C59514447 (with A2C59512082) |
| MINI | MINI (R50 / R53) | 00 - 07 | MINI IHKA | A2C59514447 |
| MINI | MINI (R55 / R56 / R57 / R60) | 06 - | MINI IHS, MINI IHKS, MINI IHKA (CAN) | A2C59514447 |
| Nissan | Navara | 04 - | HVAC CAN | A2C59514447 |
| Peugeot | 206 | 00 - | Behr GKR | A2C59514447 |
| Peugeot | 206 | 03 - | Clim T12001 | A2C59514447 |
| Peugeot | 307 | 00 - | Behr | A2C59514447 |
| Peugeot | 307 II | 04 - | Mono-Zone T5 CAN | A2C59514447 |
| Peugeot | 406 | 99 - 04 | Valeo | A2C59514447 |
| Peugeot | 407 | 05 - | Mono-Zone D2 CAN / Bi-Zone D2 CAN | A2C59514447 |
| Peugeot | 607 | 99 - | Valeo | A2C59514447 |
| Peugeot | 807 | 02 - 06 | Regulee V | A2C59514447 |
| Peugeot | 807 | 05 - | Mono-Zone V CAN | A2C59514447 |
| Peugeot | 4007 | 07 - | Clim Mitsubishi CAN | A2C59514447 |
| Renault | Clio III | 06 - | Air Conditioning | A2C59514447 |
| Renault | Espace IV | 02 - | Controlled AC | A2C59514447 |
| Renault | Laguna I | 98 - 99 | BEHR | A2C59514447 |
| Renault | Laguna II | 99 - 05 | Valeo 4 | A2C59514447 |
| Renault | Laguna II | 99 - 05 | Valeo 5 | A2C59514447 |
| Renault | Laguna II | 99 - 05 | Controlled AC | A2C59514447 |
| Renault | Laguna III | 08 - | Air Conditioning 0007-04 | A2C59514447 |
| Renault | Laguna III | 08 - | Air Conditioning 0008-04 | A2C59514447 |
| Renault | Megane | 00 - 03 | J64 | A2C59514447 |
| Renault | Megane II | 03 - | Controlled AC | A2C59514447 |
| Renault | Scenic | 00 - 03 | J64 | A2C59514447 |
| Renault | Scenic II | 03 - | Controlled AC | A2C59514447 |
| Renault | Twingo I | 07 - | Air Conditioning 0001-44 | A2C59514447 |
| Seat | Alhambra | 96 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Altea | 04 - | CAN | A2C59514447 |
| Seat | Arosa | 97 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Cordoba | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Ibiza | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 00 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 04 - | CAN | A2C59514447 |
| Seat | Toledo | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Toledo III | 04 - | CAN | A2C59514447 (with A2C59512079) |
| Skoda | Fabia | 00 - 07 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Fabia II | 07 - | CAN | A2C59514447 (with A2C59512079) |
| Skoda | Octavia | 96 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Octavia II | 04 - | CAN | A2C59514447 |
| Skoda | Roomster | 06 - | CAN | A2C59514447 (with A2C59512079) |
| Skoda | Superb | 02 - | KWP1281 / KW2000 | A2C59514447 |
| Skoda | Yeti | 10 - | CAN | A2C59514447 |
| Toyota | Auris | 07 - | AC CAN | A2C59514447 |
| Toyota | Prius (NHW20) | 04 - 09 | AC KW2 9600 | A2C59514447 |
| Toyota | RAV4 III (CA30W) | 06 - | AC CAN | A2C59514447 |
| Toyota | Yaris II | 06 - | AC CAN | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK CLIMATE CONTROL

| Make | Model | From/To | System | Harness Required |
|-------|--------------------------|---------|------------------|--------------------------------|
| Volvo | C70 Convertible/Coupe | 99 - 05 | CCM X70 | A2C59514447 |
| Volvo | S40 | 01 - 04 | CCM 1 | A2C59514447 |
| Volvo | S40 | 04 - 06 | CCM 2 | A2C59514447 |
| Volvo | V40 | 01 - 04 | CCM 1 | A2C59514447 |
| Volvo | V50 | 03 - 08 | CCM 2 | A2C59514447 |
| Volvo | S60 | 01 - 05 | CCM 2 | A2C59514447 |
| Volvo | S70 | 99 - 00 | CCM X70 | A2C59514447 |
| Volvo | V70 | 99 - 00 | CCM X70 | A2C59514447 |
| Volvo | V70 | 00 - 07 | CCM 2 | A2C59514447 |
| Volvo | XC70 | 00 - 06 | CCM 2 | A2C59514447 |
| Volvo | S80 | 99 - 06 | CCM 2 | A2C59514447 |
| Volvo | XC90 | 02 - 06 | CCM 2 | A2C59514447 |
| VW | Amorak | 10 - | CAN | A2C59514447 |
| VW | Beetle | 99 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Bora | 98 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Bora | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Cabrio | 95 - 02 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Caddy | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Corrado | 91 - 95 | KWP1281 / KW2000 | A2C59514447 |
| VW | EOS | 05 - | CAN | A2C59514447 |
| VW | Eurovan | 99 - 03 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Golf/GTI | 92 - 03 | KWP1281 / KW2000 | A2C59514447 |
| VW | Golf/GTI | 03 - | CAN | A2C59514447 |
| VW | Golf Plus | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Jetta | 92 - 04 | KWP1281 / KW2000 | A2C59514447 |
| VW | Jetta | 05 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Lupo | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 94 - 05 | KWP1281 / KW2000 | A2C59514447 |
| VW | Passat | 05 - | CAN | A2C59514447 |
| VW | Phaeton | 03 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Polo | 98 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Scirocco III | 09 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Sharan | 95 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 03 - 06 | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 07 - | CAN | A2C59514447 |
| VW | Touran | 03 - | CAN | A2C59514447 (with A2C59512079) |
| VW | Transporter/Caravelle | 92 - 04 | KWP1281 / KW2000 | A2C59514447 |
| VW | Transporter/Caravelle T5 | 04 - | CAN | A2C59514447 |
| VW | Vento | 92 - 98 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|------------|--------------------------------|--------------|---------|---|------------------|
| Alfa Romeo | 147 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 147 | | | Bosch EDC16 CF3/EObD Diesel Inj (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 156 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 156 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 159 | | | Bosch EDC16C39 CF4/EObD (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 159 | | | Bosch EDC16C39 CF4/EObD (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 159 | | | Bosch EDC16C39 CF4/EObD (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 166 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 166 | | | Bosch EDC16 CF3/EObD Diesel Inj (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 156 '02 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 156 '02 | | | Bosch EDC15 CF3/EObD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Alfa Romeo | 156 '02 | | | Bosch EDC16 CF3/EObD Diesel Inj (1.9/2.4) | A2C59514447 |
| Alfa Romeo | 156 '02 | | | Bosch EDC16 CF3/EObD Diesel Inj (1.9/2.4) | A2C59514447 |
| Alfa Romeo | GT | | | Bosch EDC16 CF3/EObD Diesel Inj (1.9/2.4) | A2C59514447 |
| Alfa Romeo | MiTo | | | Marelli 6F3 EOBD CAN Diesel Injection (EP eng. 1.3 JTD) 2 | A2C59514447 |
| Audi | A1 (8X) | CAYB | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A1 (8X) | CAYC | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CAYB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CAYC | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CBAA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CFFA | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CBAB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CFFB | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CJLA | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CBBB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A3 / S3 (8P) | CFGB | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAGB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAGA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CMEA | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAHB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAHA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAGC | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAMB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CGKB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAMA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CGKA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CCWB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CAPA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CCLA | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A4 / S4 / RS4 / Cabriolet (B8) | CCWA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAGB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAGA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAHB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAHA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CGKB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAMB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CGKA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CAMA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CCWB | 08 - | VAG Injector Programming | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|---------|-------------------------|--------------|---------------|---|------------------|
| Audi | A5 / S5 (B8) | CAPA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A5 / S5 (B8) | CCWA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CAGB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CAHB | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CAHA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CANB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CAND | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CANA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CANC | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | BPP | 05 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | BSG | 05/04 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CDYB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | ASB | 07 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CDYA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | CDYC | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | BMK | 05/04 - 06/06 | VAG Injector Programming | A2C59514447 |
| Audi | A6 / S6 / RS6 (C6 - 4F) | BNG | 05 - | VAG Injector Programming | A2C59514447 |
| Audi | A8/S8 (D4 - 4H) | CDSB | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CAGB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CAGA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CAHB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CAHA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CCWB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q5 (8R) | CCWA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CJGC | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CJMA | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CASB | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CJGA | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CASA | 08 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CCMA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | BUG | 03/06 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | BUN | 03/06 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CCFC | 11 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | BAR | 03/06 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | BTR | 07 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CCFA | 10 - | VAG Injector Programming | A2C59514447 |
| Audi | Q7 (4L) | CCGA | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | TT (8J) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| Audi | TT (8J) | CFGB | 11 - | VAG Injector Programming | A2C59514447 |
| Citroen | Jumper | RHV 2.0 | | Bosch EDC15C7 | A2C59514447 |
| Citroen | Jumper | 4HY 2.2 | | Bosch EDC15C7 | A2C59514447 |
| Citroen | Jumper | 8140.43S 2.8 | | Bosch EDC15C7 | A2C59514447 |
| Citroen | Relay | RHV 2.0 | | Bosch EDC15C7 | A2C59514447 |
| Citroen | Relay | 4HY 2.2 | | Bosch EDC15C7 | A2C59514447 |
| Citroen | Relay | 8140.43S 2.8 | | Bosch EDC15C7 | A2C59514447 |
| Fiat | 500 | | 07 - | Marelli 6F3 EOBD CAN Diesel Injection (EP eng. 1.3 JTD) 2 | A2C59514447 |
| Fiat | Bravo-Brava | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Croma '05 | | | Bosch EDC16C39 CF4/EOBD (1.9/2.4) | A2C59514447 |
| Fiat | Croma '05 | | | Bosch EDC16C39 CF4/EOBD (1.9/2.4) | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|---------|--------------|--------------|---------|--|------------------|
| Fiat | Croma '05 | | | Bosch EDC16C39 CF4/EOBD (1.9/2.4) | A2C59514447 |
| Fiat | Doblo | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Doblo | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Fiat | Doblo | | | Marelli Diesel Injection 6F3 EOBD (eng. 1.3 JTD) | A2C59514447 |
| Fiat | Ducato | | | Bosch EDC15 CF3/EOBD (eng. 2.0 / 2.3 / 2.8) | A2C59514447 |
| Fiat | Ducato | | | Bosch EDC15 CF3/EOBD (eng. 2.0 / 2.3 / 2.8) | A2C59514447 |
| Fiat | Ducato RST | | | Bosch EDC15 CF3/EOBD (eng. 2.0 / 2.3 / 2.8) | A2C59514447 |
| Fiat | Ducato RST | | | Bosch EDC15 CF3/EOBD (eng. 2.0 / 2.3 / 2.8) | A2C59514447 |
| Fiat | Ducato RST | | | Bosch EDC15 CF3/EOBD (eng. 2.0 / 2.3 / 2.8) | A2C59514447 |
| Fiat | Grande Punto | | 05 - | Bosch Diesel Injection EDC16C39 CF4/EOBD CAN (EP eng. 1.9) | A2C59514447 |
| Fiat | Grande Punto | | 05 - | Marelli Diesel Injection 6F3 EOBD CAN (EP eng. 1.3 JTD) | A2C59514447 |
| Fiat | Idea | | | Bosch EDC16C9 CF3/EOBD Diesel (1.9 eng) | A2C59514447 |
| Fiat | Idea | | | Bosch EDC16C9 CF4/EOBD Diesel Inj (1.9 eng) | A2C59514447 |
| Fiat | Idea | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Fiat | Idea | | | Marelli Diesel Injection 6F3 EOBD (eng. 1.3 JTD) | A2C59514447 |
| Fiat | Marea | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Mulipla | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Mulipla | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Palio RST | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Palio RST | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Fiat | Palio RST | | | Marelli Diesel Injection 6F3 EOBD (eng. 1.3 JTD) | A2C59514447 |
| Fiat | Panda | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Fiat | Panda | | | Marelli Diesel Injection 6F3 EOBD (eng. 1.3 JTD) | A2C59514447 |
| Fiat | Punto | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Punto | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Punto | | | Bosch EDC16 CF3/EOBD Diesel Inj (1.9/2.4) | A2C59514447 |
| Fiat | Punto | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Fiat | Stilo | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Fiat | Stilo | | | Bosch EDC16 CF3/EOBD Diesel Inj (1.9/2.4) | A2C59514447 |
| Ford | Fiesta | | 02 - 08 | PCM | A2C59514447 |
| Ford | Focus | | 04 - | PCM | A2C59514447 |
| Ford | Focus C-Max | | 03 - | PCM | A2C59514447 |
| Ford | Fusion | | 02 - 08 | PCM | A2C59514447 |
| Lancia | Lybra | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Lancia | Lybra | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Lancia | Musa | | | Bosch EDC16C9 CF3/EOBD Diesel (1.9 eng) | A2C59514447 |
| Lancia | Musa | | | Bosch EDC16C9 CF4/EOBD Diesel Inj (1.9 eng) | A2C59514447 |
| Lancia | Musa | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Lancia | Thesis | | | Bosch EDC15 CF3/EOBD Diesel Injection (1.9 / 2.4) | A2C59514447 |
| Lancia | Thesis | | | Bosch EDC16 CF3/EOBD Diesel Inj (1.9/2.4) | A2C59514447 |
| Lancia | Ypsilon | | | Marelli 6JF EOBD Diesel Inj (eng 1.3 JTD) | A2C59514447 |
| Peugeot | Boxer | RHV 2.0 | | Bosch EDC15C7 | A2C59514447 |
| Peugeot | Boxer | 4HY 2.2 | | Bosch EDC15C7 | A2C59514447 |
| Peugeot | Boxer | 8140.43S 2.8 | | Bosch EDC15C7 | A2C59514447 |
| Renault | Avantime | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Avantime | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Avantime | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Clio II | | 01 - 06 | LVCR Delphi | A2C59514447 |
| Renault | Clio III | | 06 - | Delphi DDCR | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|---------|--------------------------|--------------|---------|------------------|------------------|
| Renault | Clio III | | 06 - | Delphi DDCR | A2C59514447 |
| Renault | Clio III | | 06 - | Delphi DDCR | A2C59514447 |
| Renault | Espace | | 00 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Espace | | 00 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Espace | | 00 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Espace | | 00 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Espace | | 00 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Espace IV | | 06 - | Bosch EDC16 CP33 | A2C59514447 |
| Renault | Espace IV | | 06 - | Bosch EDC16 CP33 | A2C59514447 |
| Renault | Espace IV | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Espace IV | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Espace IV | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Kangoo | | 01 - 08 | LVCR Delphi | A2C59514447 |
| Renault | Kangoo 4X4 | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Kangoo 4X4 | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Kangoo III | | 08 - | Delphi DDCR | A2C59514447 |
| Renault | Kangoo III | | 08 - | Delphi DDCR | A2C59514447 |
| Renault | Laguna Grand Tour Nevada | | 99-01 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 06 - | Bosch EDC16 | A2C59514447 |
| Renault | Laguna II | | 06 - | Bosch EDC16 CP33 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Laguna II | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Master | | 01 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Megane | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane II | | 02 - | Bosch EDC16 | A2C59514447 |
| Renault | Megane II | | 02 - | Bosch EDC16 | A2C59514447 |
| Renault | Megane II | | 02 - | Bosch EDC16 CP33 | A2C59514447 |
| Renault | Megane II | | 02 - | Delphi DDCR | A2C59514447 |
| Renault | Megane II | | 02 - | Delphi DDCR | A2C59514447 |
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|---------|---------------------|--------------|---------|--------------------------|------------------|
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Megane Scenic | | 01 - 03 | EDC15 C3 | A2C59514447 |
| Renault | Modus | | 03 - | Delphi DDCR | A2C59514447 |
| Renault | Modus | | 03 - | Delphi DDCR | A2C59514447 |
| Renault | Scenic II | | 02 - | Bosch EDC16 | A2C59514447 |
| Renault | Scenic II | | 02 - | Bosch EDC16 | A2C59514447 |
| Renault | Scenic II | | 02 - | Bosch EDC16 CP33 | A2C59514447 |
| Renault | Scenic II | | 02 - | Delphi DDCR | A2C59514447 |
| Renault | Scenic II | | 02 - | Delphi DDCR | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Trafic | | 03 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Twingo II | | 07 - | Delphi DDCR | A2C59514447 |
| Renault | Velsatis | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Velsatis | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Velsatis | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Velsatis | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Renault | Velsatis | | 02 - 05 | EDC15 C3 | A2C59514447 |
| Seat | Altea | CAYC | 07 - 10 | VAG Injector Programming | A2C59514447 |
| Seat | Altea | CAYB | 11 - | VAG Injector Programming | A2C59514447 |
| Seat | Altea | CAYC | 11 - | VAG Injector Programming | A2C59514447 |
| Seat | Ibiza (6J) | CAYB | 09 - | VAG Injector Programming | A2C59514447 |
| Seat | Ibiza (6J) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| Seat | Leon II (1P) | CAYC | 06 - 10 | VAG Injector Programming | A2C59514447 |
| Seat | Leon II (1P) | CAYB | 11 - | VAG Injector Programming | A2C59514447 |
| Seat | Leon II (1P) | CAYC | 11 - | VAG Injector Programming | A2C59514447 |
| Skoda | Fabia II (5J) | CAYA | 11 - | VAG Injector Programming | A2C59514447 |
| Skoda | Fabia II (5J) | CAYB | 11 - | VAG Injector Programming | A2C59514447 |
| Skoda | Fabia II (5J) | CAYC | 11 - | VAG Injector Programming | A2C59514447 |
| Skoda | Octavia II (1Z) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| Skoda | Octavia II (1Z) | CEGA | 08 - | VAG Injector Programming | A2C59514447 |
| Skoda | Roomster (5J) 2006> | CAYA | 10 - | VAG Injector Programming | A2C59514447 |
| Skoda | Roomster (5J) 2006> | CAYB | 10 - | VAG Injector Programming | A2C59514447 |
| Skoda | Roomster (5J) 2006> | CAYC | 10 - | VAG Injector Programming | A2C59514447 |
| Skoda | Superb (3T) | CAYC | 08 - | VAG Injector Programming | A2C59514447 |
| Skoda | Superb (3T) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| Skoda | Yeti (5L) | CAYC | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Caddy (2K) | CAYD | 09 - 11 | VAG Injector Programming | A2C59514447 |
| VW | Caddy (2K) | CAYE | 09 - 11 | VAG Injector Programming | A2C59514447 |
| VW | Golf Mk V1(5k) | CAYB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Mk V1(5k) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Mk V1(5k) | CBAA | 09 - | VAG Injector Programming | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK Diesel

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|------|------------------------|--------------|---------|--------------------------|------------------|
| VW | Golf Mk V1(5k) | CBAB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Mk V1(5k) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Mk V1(5k) | CBDC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CAYB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBAA | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBDA | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBAB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBDB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Golf Plus (52) | CBDC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Jetta MK V (1K) | CAYB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Jetta MK V (1K) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Jetta MK VI (1K) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat 35 (CC) | CBAA | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat 35 (CC) | CBAB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat 35 (CC) | CBAC | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Passat 35 (CC) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CAYC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CBAA | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CBAB | 08 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CBAC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CBBB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Passat Mk VI (B6 - 3C) | CBDC | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Polo (6R) | CAYA | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Polo (6R) | CAYB | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Polo (6R) | CAYC | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Scirocco III (13) | CBBB | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Scirocco III (13) | CBDB | 09 - | VAG Injector Programming | A2C59514447 |
| VW | Tiguan (5N) | CBAA | 08 - | VAG Injector Programming | A2C59514447 |
| VW | Tiguan (5N) | CBAB | 08 - | VAG Injector Programming | A2C59514447 |
| VW | Tiguan (5N) | CBBA | 08 - | VAG Injector Programming | A2C59514447 |
| VW | Tiguan (5N) | CBBB | 08 - | VAG Injector Programming | A2C59514447 |
| VW | Touran | CAYB | 10 - | VAG Injector Programming | A2C59514447 |
| VW | Touran | CAYC | 10 - | VAG Injector Programming | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK EPB - Electronic Parking Brake

| Make | Model | From/To | System | Harness Required |
|------------|--------------------------|------------|--------------------------------------|--------------------------------|
| Audi | A4 | 05 - | EPB | A2C59514447 |
| Audi | S4 | 04 - | EPB | A2C59514447 |
| Audi | A5 | 07 - | EPB | A2C59514447 |
| Audi | S5 | 08 - | EPB | A2C59514447 |
| Audi | A6 | 04 - | EPB | A2C59514447 |
| Audi | S6 | 04 - | EPB | A2C59514447 |
| Audi | A8 | 04 - | EPB | A2C59514447 |
| Audi | Q5 | 09 - | EPB | A2C59514447 |
| BMW | 5 Series (F07/F10/F11) | 01/09 - | EMF 10 | A2C59514447 |
| BMW | 6 Series (F12) | 10/09 - | EMF 10 | A2C59514447 |
| BMW | 7 Series (E65) | 02 - 03/07 | EMF 65 | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | EMF 65 (D-CAN) | A2C59514447 |
| BMW | 7 Series (F01/F02/F04) | 06/07 - | EMF 01 | A2C59514447 |
| BMW | X3 (F25) | 06/09 - | EMF | A2C59514447 |
| BMW | X5 (E70) | 10/06 - | EMF 70 | A2C59514447 |
| BMW | X6 (E71) | 01/08 - | EMF 70 | A2C59514447 |
| BMW | Z4 (E89) | 01/08 - | EMF 89 | A2C59514447 |
| Ford | C-Max | 03 - | EPB | A2C59514447 |
| Ford | Galaxy | 06 - | EPB | A2C59514447 |
| Ford | Mondeo | 07 - | EPB | A2C59514447 |
| Ford | S-Max | 06 - | EPB | A2C59514447 |
| Jaguar | S-Type | 99 - 08 | Parking Brake CAN | A2C59514447 |
| Jaguar | XF (X250) | 08 - | PBM A3, PBM A4 | A2C59514447 |
| Jaguar | XJ/XJR (X350) | 03 - 09 | Parking Brake SCP, Parking Brake CAN | A2C59514447 |
| Jaguar | XK/XKR (X150) | 06 - | PBM A3, PBM A4 | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | PBM | A2C59514447 |
| Land Rover | Discovery IV (L319) | 10 | PBM | A2C59514447 |
| Land Rover | Range Rover (L322) | 07 - 09 | PBM | A2C59514447 |
| Land Rover | Range Rover (L322) | 10 | PBM | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | PBM | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 10 | PBM | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | SBC (CAN) | A2C59514447 |
| Mercedes | CLS (W219) | 04 - | SBC (CAN) Brake Bleed | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | Sensotronic BC | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | Sensotronic BC Brake Bleed | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | SBC (CAN) | A2C59514447 |
| Mercedes | E Class (W211) | 02 - | SBC (CAN) Brake Bleed | A2C59514447 |
| Mercedes | SL (R230) | 03 - 06 | Sensotronic BC | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 03 - 06 | SBC (CAN) | A2C59514447 |
| Mercedes | SLR (199) | 04 - | Sensotronic BC | A2C59514447 |
| Renault | Koleos | 08 - | EPB DD02-04 | A2C59514447 |
| Renault | Laguna III | 08 - | EPB DD02-04 | A2C59514447 |
| Renault | Megane II | 03 - | EPB | A2C59514447 |
| Renault | Scenic II | 02 - | EPB | A2C59514447 |
| Renault | Espace IV | 02 - | EPB | A2C59514447 |
| Renault | Vel Satis | 01 - | EPB | A2C59514447 |
| Volvo | S80 | 07 - | PBM | A2C59514447 |
| Volvo | V70 | 08 - | PBM | A2C59514447 |
| Volvo | XC60 | 09 - | PBM | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK EPB - Electronic Parking Brake

| Make | Model | From/To | System | Harness Required |
|-------------|--------------|----------------|---------------|-------------------------|
| Volvo | XC70 | 08 - | PBM | A2C59514447 |
| VW | Passat | 05 - | EPB | A2C59514447 |
| VW | Tiguan | 07 - | EPB | A2C59514447 |

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|------|--------------|-------------|--------------|---------|---------|---------|------------------|
| Audi | A3 | BKD | GYN | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AXX | HBQ | 11/2005 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AZV | HLE | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BKD | HFQ | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AXX | HRW | 05/2004 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AZV | HQL | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AXX | HUT | 05/2004 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BWA | HXW | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BUY | HYC | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BKD | HXS | 11/2004 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BXE | HXU | 06/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | AZV | JPJ | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BXE | JPL | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BYT | JPT | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BWA | JPP | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BUY | JEQ | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BMN | JPQ | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BMJ | GYC | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BMJ | HUW | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BUB | HXZ | 09/2003 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BUB | JPZ | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Audi | A3 | CAXC | KHN | 03/2008 | 06/2008 | 7 gears | A2C59514447 |
| Audi | A3 | | LKG | 03/2008 | 06/2008 | 7 gears | A2C59514447 |
| Audi | A3 | BUB | KDE | 06/2007 | 11/2007 | 6 gears | A2C59514447 |
| Audi | A3 | BUB | KNL | 11/2007 | 06/2008 | 6 gears | A2C59514447 |
| Audi | A3 | BYT | JPT | 06/2007 | 06/2008 | 6 gears | A2C59514447 |
| Audi | A3 | AZV | KCU | 06/2007 | 06/2008 | 6 gears | A2C59514447 |
| Audi | A3 | BLS | KCW | 06/2007 | 06/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | BZB | KDD | 04/2008 | 04/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | CAWB | KNC | 04/2008 | 04/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | CAWB | KMX | 04/2008 | 04/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | BZB | KNG | 04/2008 | 04/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | BZB | KPR | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | CAWB | KPV | 06/2008 | 11/2008 | 6 gears | A2C59514447 |
| Audi | A3 Cabriolet | CBAA | KQC | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| Audi | A4 | CDNC | LZL | 11/2008 | | 7 gears | A2C59514447 |
| Audi | A4 | | KSF | | | 7 gears | A2C59514447 |
| Audi | A4 | | LHL | | | 7 gears | A2C59514447 |
| Audi | A4 | CAKA | LJD | 03/2009 | | 7 gears | A2C59514447 |
| Audi | A4 | | LHK | | | 7 gears | A2C59514447 |
| Audi | A5 | CAEB | LZL | 06/2008 | | 7 gears | A2C59514447 |
| Audi | A5 | CAHA | KSF | 08/2008 | | 7 gears | A2C59514447 |
| Audi | A5 | CDNB | LHL | 09/2008 | | 7 gears | A2C59514447 |
| Audi | TT | BHE | GYU | 04/2003 | | 6 gears | A2C59514447 |
| Audi | TT | BHE | GYW | 04/2003 | | 6 gears | A2C59514447 |
| Audi | TT | BHE | HAH | 04/2003 | | 6 gears | A2C59514447 |
| Audi | TT | BHE | HYB | 04/2003 | | 6 gears | A2C59514447 |
| Audi | TT | BWA | HXW | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | BPY | JPP | 08/2006 | | 6 gears | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|------|-------------|-------------|--------------|---------|---------|----------------|------------------|
| Audi | TT | BPY | KCZ | 11/2007 | | 6 gears | A2C59514447 |
| Audi | TT | BPY | KNC | 11/2007 | | 6 gears | A2C59514447 |
| Audi | TT | BPY | KPV | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | BUB | HXZ | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | BUB | JPZ | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | BUB | KDE | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | BUB | KNL | 08/2006 | | 6 gears | A2C59514447 |
| Audi | TT | CDLA | KRF | 05/2008 | | 6 gears | A2C59514447 |
| Audi | TT | CDLB | KNN | 08/2006 | | 6 gears | A2C59514447 |
| Audi | Q5 | CAHA | LHE | 11/2008 | | 7 gears | A2C59514447 |
| Audi | Q5 | CDNC | LHF | 11/2008 | | 7 gears | A2C59514447 |
| Audi | Q5 | CCWB | LHG | 11/2008 | | 7 gears | A2C59514447 |
| Audi | Q5 | CAHA | LHH | 11/2008 | | 7 gears | A2C59514447 |
| Audi | R8 | BYH | KBC | 04/2007 | | 7 gears | A2C59514447 |
| Audi | R8 | BYH | LFR | 03/2008 | | 7 gears | A2C59514447 |
| GM | Corsa | Z10XE | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z10XE ECO | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z10XEP | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z10XEP ECO | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z12XE | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z12XEP | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z13DT | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | Z14XEP | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | T18NE | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa | X18NE | | | | MTA Easytronic | A2C59514447 |
| GM | Corsa Combo | Z13DTJ | | | | MTA Easytronic | A2C59514447 |
| GM | Meriva | Z16XE | | | | MTA Easytronic | A2C59514447 |
| GM | Meriva | Z16XEP | | | | MTA Easytronic | A2C59514447 |
| GM | Meriva | Z18XE | | | | MTA Easytronic | A2C59514447 |
| GM | Meriva | T18NE | | | | MTA Easytronic | A2C59514447 |
| GM | Meriva | X18NE1 | | | | MTA Easytronic | A2C59514447 |
| Seat | Altea | AZV | HJP | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BMM | HXT | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BKD | JPK | 11/2006 | 06/2007 | 6 gears | A2C59514447 |
| Seat | Altea | BMM | JPK | 11/2006 | 06/2007 | 6 gears | A2C59514447 |
| Seat | Altea XL | BKD | JPK | 05/2007 | 05/2007 | 6 gears | A2C59514447 |
| Seat | Altea XL | BKD | JPK | 11/2006 | 06/2007 | 6 gears | A2C59514447 |
| Seat | Altea XL | BMM | JPK | 11/2006 | 06/2007 | 6 gears | A2C59514447 |
| Seat | Altea | BWA | JPP | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | AZV | KCV | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BKD | KCV | 05/2007 | 10/2007 | 6 gears | A2C59514447 |
| Seat | Altea | BWA | KCZ | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BLS | KCW | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BLS | KMZ | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | | HXW | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BWA | KNC | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BMM | KMY | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BLS | KPQ | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | AZV | KPT | 05/2006 | 11/2006 | 6 gears | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|-------|---------|-------------|--------------|---------|---------|---------|------------------|
| Seat | Altea | BWA | KPV | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | BMM | LQW | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Altea | | LQS | | | 6 gears | A2C59514447 |
| Seat | Altea | BWA | LQZ | 05/2006 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | AZV | HJP | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | AZV | HQM | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Seat | Toledo | BKD | HXT | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Seat | Toledo | BLS | KCW | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BKD | KCV | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BWA | KCZ | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BLS | KMZ | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BKD | JPK | 11/2006 | 05/2007 | 6 gears | A2C59514447 |
| Seat | Toledo | BWA | JPP | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | | HXW | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BWA | KNC | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BMM | KMY | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BLS | KPQ | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BMM | KPT | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BWA | KPV | 09/2004 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Toledo | BMM | LQW | 11/2008 | | 6 gears | A2C59514447 |
| Seat | Toledo | | LQS | | | 6 gears | A2C59514447 |
| Seat | Toledo | BWA | LQZ | 11/2008 | | 6 gears | A2C59514447 |
| Seat | Leon | BKD | HXT | 11/2005 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Leon | BMM | HQM | 11/2005 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Leon | BWA | JPP | 06/2006 | 06/2007 | 6 gears | A2C59514447 |
| Seat | Leon | BKD | JPK | 11/2005 | 11/2006 | 6 gears | A2C59514447 |
| Seat | Leon | BWA | KCZ | 06/2007 | 11/2007 | 6 gears | A2C59514447 |
| Seat | Leon | BKD | KCV | 05/2007 | 11/2007 | 6 gears | A2C59514447 |
| Seat | Leon | BLS | KCW | 06/2007 | 11/2007 | 6 gears | A2C59514447 |
| Seat | Leon | BLS | KMZ | 11/2007 | 05/2008 | 6 gears | A2C59514447 |
| Seat | Leon | BKD | KMY | 11/2007 | 05/2008 | 6 gears | A2C59514447 |
| Seat | Leon | BWA | KNC | 11/2007 | 11/2008 | 6 gears | A2C59514447 |
| Seat | Leon | BLS | KPQ | 05/2008 | | 6 gears | A2C59514447 |
| Seat | Leon | BMM | KPT | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| Seat | Leon | BWA | KPV | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| Seat | Leon | BKD | LQW | 11/2008 | | 6 gears | A2C59514447 |
| Seat | Leon | BWA | LQZ | 11/2008 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BKC | HLH | 03/2004 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BKC | HQN | 03/2004 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BLS | HXU | 03/2004 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BKC | HXU | 03/2004 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BXE | HXU | 03/2004 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BXE | JPL | 01/2005 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BLS | HXU | 01/2005 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BXE | KCW | 01/2005 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BLS | KCW | 01/2005 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BXE | KCW | 05/2007 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BLS | KCW | 05/2007 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BLS | KMZ | 06/2007 | | 6 gears | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|-------|-----------|-------------|--------------|---------|---------|---------|------------------|
| Skoda | Oktavia | BXE | KMZ | 06/2007 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BSE | KGJ | 11/2008 | | 6 gears | A2C59514447 |
| Skoda | Oktavia | BSF | KGJ | 11/2008 | | 6 gears | A2C59514447 |
| Skoda | Superb | BMP | KMX | 03/2008 | | 6 gears | A2C59514447 |
| Skoda | Superb | CBBB | KPS | 05/2008 | | 6 gears | A2C59514447 |
| Skoda | Superb | BMP | KQC | 05/2008 | | 6 gears | A2C59514447 |
| Skoda | Superb | CDVA | LHT | 09/2008 | | 6 gears | A2C59514447 |
| Skoda | Superb | CDAA | KHP | 09/2008 | | 7 gears | A2C59514447 |
| VW | Scirocco | CAVD | LKP | 11/2008 | | 7 gears | A2C59514447 |
| VW | Scirocco | CBDB | KQC | 08/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Scirocco | CBDB | LQV | 11/2008 | | 6 gears | A2C59514447 |
| VW | Scirocco | CAWB | KPV | 08/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Beetle | 1C | HQP | 07/2005 | | 6 gears | A2C59514447 |
| VW | EOS | | LKG | 05/2008 | | 7 gears | A2C59514447 |
| VW | EOS | CAWB | KPU | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | EOS | CBAB | KQC | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Jetta | CAXA | KHN | 02/2008 | 02/2008 | 7 gears | A2C59514447 |
| VW | Jetta | BLS | KHM | 02/2008 | 05/2008 | 7 gears | A2C59514447 |
| VW | Touran | BKC | HLH | 08/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKC | GYR | 08/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKC | GPV | 08/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKD | GYP | 06/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKD | GPQ | 06/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKD | HJP | 06/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKD | HLG | 06/2003 | 05/2005 | 6 gears | A2C59514447 |
| VW | Touran | BKD | HQM | 06/2005 | 11/2006 | 6 gears | A2C59514447 |
| VW | Touran | BKC | HQN | 06/2005 | 11/2006 | 6 gears | A2C59514447 |
| VW | Touran | BKT | HXT | 06/2005 | 11/2006 | 6 gears | A2C59514447 |
| VW | Touran | BLS | HXU | 06/2005 | 11/2006 | 6 gears | A2C59514447 |
| VW | Touran | BMN | HYC | 12/2005 | 11/2006 | 6 gears | A2C59514447 |
| VW | Touran | BKD | JPK | 11/2006 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BMN | KCV | 06/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BLS | KCW | 06/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BMN | KDA | 05/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BLG | KDC | 05/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BLG | JPS | 11/2006 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BMN | KMW | 06/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BKD | KMY | 11/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BLS | KMZ | 11/2007 | 05/2008 | 6 gears | A2C59514447 |
| VW | Touran | BLS | JPL | 11/2006 | 05/2008 | 6 gears | A2C59514447 |
| VW | Passat CC | BWS | LHT | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat CC | BWS | LRJ | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat CC | BZB | LKN | 11/2008 | 05/2009 | 7 gears | A2C59514447 |
| VW | Passat | AXZ | HXX | 09/2005 | 05/2007 | 6 gears | A2C59514447 |
| VW | Passat | AXZ | HBR | 09/2005 | 05/2007 | 6 gears | A2C59514447 |
| VW | Passat | AXZ | JPY | 09/2005 | 05/2007 | 6 gears | A2C59514447 |
| VW | Passat | | KJL | 05/2007 | 02/2008 | 6 gears | A2C59514447 |
| VW | Passat | | KNM | 02/2008 | 05/2008 | 6 gears | A2C59514447 |
| VW | Passat | | LHQ | 02/2008 | 05/2008 | 6 gears | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|------|-----------|-------------|--------------|---------|---------|---------|------------------|
| VW | Passat | | LHS | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat | | LRH | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat | | KPZ | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat | | LRE | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat | | LQV | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat | | KQC | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat | | KPS | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat | | LQT | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat | | LRH | 11/2008 | | 6 gears | A2C59514447 |
| VW | Passat | | KPZ | 05/2008 | 11/2008 | 6 gears | A2C59514447 |
| VW | Passat | | LKG | 05/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Passat | | LKM | 11/2008 | 05/2009 | 7 gears | A2C59514447 |
| VW | Passat | | LKN | 11/2008 | 05/2009 | 7 gears | A2C59514447 |
| VW | Golf 4 | BFH | GYD | 12/2003 | 06/2006 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | HUV | 09/2005 | 07/2007 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | HXZ | 09/2005 | 07/2007 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | JPZ | 11/2006 | 07/2007 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | KDE | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | KNL | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BUB | KQA | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BMM | JPJ | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BWA | JPP | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BXE | JPL | 05/2007 | 11/2008 | 6 gears | A2C59514447 |
| VW | Golf 5 | BLS | LKF | 05/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 5 | CAXA | LKG | 09/2007 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 5 | CAXA | KHN | 09/2007 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 5 | BLS | KHM | 05/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 6 | CBAB | KQC | 10/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 6 | CBDC | LQV | 11/2008 | | 7 gears | A2C59514447 |
| VW | Golf 6 | CAVD | KUT | 10/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 6 | CAVD | LKP | 10/2008 | | 7 gears | A2C59514447 |
| VW | Golf 6 | CAXA | LKM | 11/2008 | | 7 gears | A2C59514447 |
| VW | Golf 6 | CAXA | LKG | 10/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf 6 | BSF | LKJ | 10/2008 | | 7 gears | A2C59514447 |
| VW | Golf Plus | BKD | JPK | 05/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BLS | JPL | 05/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BLG | JPS | 05/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BKD | KVC | 05/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BXE | KCW | 05/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BLG | KDC | 05/2007 | 05/2007 | 6 gears | A2C59514447 |
| VW | Golf Plus | KCW | KMZ | 11/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BKD | KMY | 11/2008 | | 6 gears | A2C59514447 |
| VW | Golf Plus | BLG | KNF | 11/2007 | | 6 gears | A2C59514447 |
| VW | Golf Plus | CAXA | KHN | 09/2007 | 05/2008 | 7 gears | A2C59514447 |
| VW | Golf Plus | BLS | KHM | 05/2008 | | 7 gears | A2C59514447 |
| VW | Golf Plus | CAXA | LKG | 10/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf Plus | BLS | LKF | 05/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf Plus | CAVD | KUT | 05/2008 | 11/2008 | 7 gears | A2C59514447 |
| VW | Golf Plus | BLS | LKL | 11/2008 | | 7 gears | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK G/Box - Gearbox

| Make | Model | Engine Code | Transmission | From | To | System | Harness Required |
|-------------|--------------|--------------------|---------------------|-------------|-----------|---------------|-------------------------|
| VW | Golf Plus | CAVD | LKP | 11/2008 | | 7 gears | A2C59514447 |
| VW | Golf Plus | CAXA | LKM | 11/2008 | | 7 gears | A2C59514447 |
| VW | Golf Plus | BSE | LKJ | 05/2008 | | 7 gears | A2C59514447 |

FASTCHECK SAS - Steering Angle Sensor

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|------------|------------------------------|--------------|---------|--|------------------|
| Alfa Romeo | 147 | All | 00 - 07 | Bosch 5.7 VDC, Bosch 8 VDC | A2C59514447 |
| Alfa Romeo | 156 '02 | All | 02 - 05 | Bosch 5.7 VDC | A2C59514447 |
| Alfa Romeo | 159 | All | 05 - | TRW / Lucas ESP | A2C59514447 |
| Alfa Romeo | 166 | All | 02 - 05 | Bosch 5.7 VDC | A2C59514447 |
| Alfa Romeo | Brera | All | 05 - | TRW / Lucas ESP | A2C59514447 |
| Alfa Romeo | GT | All | 04 - | Bosch 5.7 VDC, Bosch 8 VDC | A2C59514447 |
| Alfa Romeo | MiTo (ABS/ESP) | All | 08 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Alfa Romeo | MiTo (Power Steering) | All | 08 - | DELPHI (EP) 2 Power Steering | A2C59514447 |
| Alfa Romeo | Spider (939) | All | 07 - | TRW / Lucas ESP | A2C59514447 |
| Audi | A2 | 8Z | 01 - | ESP 20 | A2C59514447 |
| Audi | A2 | 8Z | 01 - | ESP Front/Allrad MK60 | A2C59514447 |
| Audi | A3 | 8L | 97 - 02 | ESP 20 | A2C59514447 |
| Audi | A3 | 8L | 02 - 03 | ESP Front MK60 | A2C59514447 |
| Audi | A3 | 8P | 04 - | ESP Front MK60 | A2C59514447 |
| Audi | A4 | 8D (B5) | 97 - 00 | ABS/ESP Front | A2C59514447 |
| Audi | A4 | 8E, 8H (B6) | 01 - 05 | ABS/ESP Front | A2C59514447 |
| Audi | A4 | 8E, 8H (B7) | 05 - | ESP 8 Front | A2C59514447 |
| Audi | A4 Cabriolet | 8E, 8H (B6) | 03 - 05 | ABS/ESP Front | A2C59514447 |
| Audi | A4 Cabriolet | 8E, 8H (B7) | 05 - | ESP 8 Front | A2C59514447 |
| Audi | A4 Quattro | 8D (B5) | 97 - 00 | ABS/ESP Allrad | A2C59514447 |
| Audi | A4 Quattro/Cabriolet Quattro | 8E, 8H (B6) | 01 - 05 | ABS/ESP Allrad | A2C59514447 |
| Audi | A4 Quattro/Cabriolet Quattro | 8E, 8H (B7) | 05 - | ESP 8 Allrad | A2C59514447 |
| Audi | A5 | | 08 - | CAN | A2C59514447 |
| Audi | S5 | | 08 - | CAN | A2C59514447 |
| Audi | A6 | 4B (C5) | 98 - 01 | ABS/ESP Front | A2C59514447 |
| Audi | A6 | 4B (C5) | 02 - 04 | ABS/ESP Front | A2C59514447 |
| Audi | A6 | 4F (C6) | 05 - | ESP 8 Front | A2C59514447 |
| Audi | A6 Quattro | 4B (C5) | 98 - 01 | ABS/ESP Allrad | A2C59514447 |
| Audi | A6 Quattro | 4B (C5) | 02 - 04 | ABS/ESP Allrad | A2C59514447 |
| Audi | A6 Quattro | 4F (C6) | 05 - | ESP 8 Allrad | A2C59514447 |
| Audi | A8 | 4D (D2) | 97 - 03 | ABS/ESP Front / Allrad | A2C59514447 |
| Audi | A8 | 4E (D3) | 03 - | ESP 5.7 Allrad | A2C59514447 |
| Audi | A8 Quattro | 4D (D2) | 97 - 03 | ABS/ESP Front / Allrad | A2C59514447 |
| Audi | A8 Quattro | 4E (D3) | 03 - | ESP 5.7 Allrad | A2C59514447 |
| Audi | Allroad Quattro (A6 4X4) | 4B (C5) | 01 - 04 | ABS/ESP Allrad | A2C59514447 |
| Audi | Q7 | 4L (7L) | 07 - | ESP Allrad MK25E1 | A2C59514447 |
| Audi | RS6 | 4B (C5) | 03 - 04 | ABS/ESP Allrad | A2C59514447 |
| Audi | RS6 | 4B (C5) | 03 - 04 | ESP 5.7 RS | A2C59514447 |
| Audi | S3 Quattro | 8L | 97 - 02 | ESP 20 | A2C59514447 |
| Audi | S3 Quattro | 8L | 02 - 03 | ESP Allrad MK60 | A2C59514447 |
| Audi | S3 Quattro | 8P | 04 - | ESP Allrad MK60 | A2C59514447 |
| Audi | S4 | 8D (B5) | 97 - 00 | ABS/ESP Allrad | A2C59514447 |
| Audi | S4 | 8E, 8H (B7) | 05 - | ESP 8 Allrad | A2C59514447 |
| Audi | S8 | 4D (D2) | 01 - 03 | ABS/ESP Front / Allrad | A2C59514447 |
| Audi | S8 | 4E (D3) | 03 - | ESP 5.7 Allrad | A2C59514447 |
| Audi | TT/Coupe | 8J | 07 - | ESP Front/Allrad MK60 | A2C59514447 |
| Audi | TT/Quattro | 8N | 99 - 02 | ESP 20 | A2C59514447 |
| Audi | TT/Quattro | 8N | 02 - 06 | ESP Front/Allrad MK60 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SAS - Steering Angle Sensor

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|---------|---|-----------------|---------------|--|--------------------------------|
| Bentley | Continental GT | | 04 - | Bosch 5.7 ESP | A2C59514447 |
| Bentley | Flying Spur | | 05 - | Bosch 5.7 ESP | A2C59514447 |
| BMW | 1 Series - 4 Cylinder | E81/E87 | 04 - 03/07 | Teves MK 60E | A2C59514447 |
| BMW | 1 Series - 6 Cylinder | E81/E87 | 04 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 1 Series - 4 Cylinder | E81/E82/E87/E88 | 03/07 - | Teves MK 60E (CAN) | A2C59514447 |
| BMW | 1 Series - 6 Cylinder | E81/E82/E87/E88 | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 3 Series | E46 | 98 - 05 | Teves DSC III MK 60 | A2C59514447 (with A2C59512084) |
| BMW | 3 Series - 4 Cylinder | E90/E91/E92/E93 | 05 - 03/07 | Teves MK 60E | A2C59514447 |
| BMW | 3 Series - 6 Cylinder | E90/E91/E92/E93 | 05 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 3 Series - AWD | E90/E91/E92/E93 | 05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | 3 Series - 4 Cylinder | E90/E91/E92/E93 | 03/07 - | Teves MK 60E (CAN) | A2C59514447 |
| BMW | 3 Series - 6 Cylinder | E90/E91/E92/E93 | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 3 Series - AWD | E90/E91/E92/E93 | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | 5 Series | E39 | 96 - 04 | ABS/DSC 5.7 | A2C59514447 (with A2C59512084) |
| BMW | 5 Series | E60/E61 | 04 - 09/05 | Bosch ABS DSC8 | A2C59514447 |
| BMW | 5 Series | E60/E61 | 09/05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | M5 | E60 | 04 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 5 Series | E60/E61 | 03/07 - | Bosch ABS DSC8 (CAN) | A2C59514447 |
| BMW | 5 Series | E60/E61 | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | M5 | E60 | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 6 Series | E63/E64 | 05 - 09/05 | Bosch ABS DSC8 | A2C59514447 |
| BMW | 6 Series | E63/E64 | 09/05 - 03/07 | Bosch ABS DSCS8 Plus | A2C59514447 |
| BMW | M6 | E63/E64 | 05 - 03/07 | Teves MK 60E5 | A2C59514447 |
| BMW | 6 Series | E63/E64 | 03/07 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | M6 | E63/E64 | 03/07 - | Teves MK 60E5 (CAN) | A2C59514447 |
| BMW | 7 Series | E38 | 94 - 02 | BOSCH ABS DSC2, BOSCH ABS DSC3 | A2C59514447 (with A2C59512084) |
| BMW | 7 Series | E65/E66 | 02 - 03/07 | ABS/DSC5.7 | A2C59514447 |
| BMW | 7 Series | E65/E66 | 03/07 - | ABS/DSC5.7 (CAN) | A2C59514447 |
| BMW | 8 Series | E31 | 90 - 99 | BOSCH ABS DSC2 | A2C59514447 (with A2C59512084) |
| BMW | X3 | E83 | 03 - 03/07 | DSC 8 X-Drive | A2C59514447 |
| BMW | X5 | E53 | 00 - 09/03 | ABS/DSC 5.7 | A2C59514447 |
| BMW | X5 | E53 | 09/03 - | DSC 8 X-Drive | A2C59514447 |
| BMW | X5 | E70 | 06 - | Bosch ABS DSCS8 Plus (CAN), Bosch EHB 3 | A2C59514447 |
| BMW | X6 | E71 | 08 - | Bosch ABS DSCS8 Plus (CAN), Bosch EHB 3 | A2C59514447 |
| BMW | Z4 | E85/E86 | 03 - 06 | Teves DSC III MK 60 | A2C59514447 |
| BMW | Z4/Z4M | E85/E86 | 06 - 03/07 | DSC MK60E5 | A2C59514447 |
| BMW | Z4 | E89 | 01/08 - | Bosch ABS DSCS8 Plus (CAN) | A2C59514447 |
| BMW | Z8 | E52 | 00 - 03 | ABS/DSC 5.7 | A2C59514447 (with A2C59512084) |
| Fiat | 500 (ABS/ESP) | | 07 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Fiat | 500 (Power Steering) | | 07 - | DELPHI (EP) 2 Power Steering | A2C59514447 |
| Fiat | Bravo '07 | | 07 - | Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Croma '05 | | 05 - | TRW / Lucas ESP | A2C59514447 |
| Fiat | Idea | | 04 - | Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Multipla | | 02 - | Bosch 5.7 VDC ABS | A2C59514447 |
| Fiat | Panda '03 | | 03 - | Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Punto '03 | | 03 - | Bosch 8 VDC ABS | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) (ABS/ESP) | | 05 - | Bosch ABS 8 ESP (EP), Bosch ABS 8 ESP 2 (EP) | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) (Power Steering) | | 05 - | DELPHI (EP) Power Steering | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SAS - Steering Angle Sensor

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|------------|-------------------------|-----------------|---------|------------------------------------|------------------|
| Fiat | Stilo | | 01 - 07 | Bosch 5.7 VDC ABS, Bosch 8 VDC ABS | A2C59514447 |
| Ford | Fiesta VI | | 08 - | ABS/ESP | A2C59514447 |
| Ford | Fusion II | | 09 - | ABS/ESP | A2C59514447 |
| Ford | Galaxy | | 06 - | ABS/ESP | A2C59514447 |
| Ford | Ka II (ABS/ESP) | | 08 - | ABS/ESP | A2C59514447 |
| Ford | Ka II (Power Steering) | | 08 - | DELPHI (EP) 2 Power Steering | A2C59514447 |
| Ford | Mondeo IV | | 07 - | ABS/ESP | A2C59514447 |
| Ford | S-Max | | 06 - | ABS/ESP | A2C59514447 |
| Ford | Transit | | 06 - | ABS/ESP | A2C59514447 |
| Lancia | Lybra | | 99 - 06 | TRW / Lucas ESP | A2C59514447 |
| Lancia | Musa | | 04 - 06 | Bosch 8 VDC ABS | A2C59514447 |
| Lancia | Thesis | | 02 - 06 | TRW / Lucas ESP | A2C59514447 |
| Lancia | Ypsilon | | 03 - 06 | TRW / Lucas ESP | A2C59514447 |
| Land Rover | Freelander II (SASM) | L359 | 07 - | SASM | A2C59514447 |
| Land Rover | Freelander II (ABS/ESP) | L359 | 07 - | ABS/ESP | A2C59514447 |
| Land Rover | Discovery III | L319 | 05 - 09 | SAS | A2C59514447 |
| Land Rover | Range Rover | L322 | 07 - 09 | SAS | A2C59514447 |
| Land Rover | Range Rover Sport | L320 | 05 - 09 | SAS | A2C59514447 |
| MINI | MINI | R50/R53 | 00 - 07 | Teves DSC III MK 60 | A2C59514447 |
| MINI | MINI | R55/R56/R57/R60 | 09/06 - | EBC 450 | A2C59514447 |
| Seat | Alhambra | 7M | 96 - 02 | ESP 20 | A2C59514447 |
| Seat | Alhambra | 7M | 02 - 05 | ESP Front MK25 | A2C59514447 |
| Seat | Altea with ESP | 5P | 05 - | ESP Front/Allrad MK60 | A2C59514447 |
| Seat | Altea without ESP | 5P | 05 - | ABS MK70 | A2C59514447 |
| Seat | Arosa | 6H | 97 - 02 | ESP 20 | A2C59514447 |
| Seat | Arosa | 6H | 02 - 05 | ESP Front MK25 | A2C59514447 |
| Seat | Cordoba | 6K | 99 - 02 | ESP 20 | A2C59514447 |
| Seat | Cordoba | 6K/6L | 02 - 06 | ESP 5.7 Front / Allrad | A2C59514447 |
| Seat | Cordoba | 6L | 06 - | ESP 8 Front / Allrad | A2C59514447 |
| Seat | Ibiza | 6K | 99 - 02 | ESP 20 | A2C59514447 |
| Seat | Ibiza | 6K/6L | 02 - 06 | ESP 5.7 Front / Allrad | A2C59514447 |
| Seat | Ibiza | 6L | 06 - | ESP 8 Front / Allrad | A2C59514447 |
| Seat | Inca | 6K | 97 - 03 | ESP 20 | A2C59514447 |
| Seat | Leon | 1M | 99 - 02 | ESP 20 | A2C59514447 |
| Seat | Leon | 1M | 02 - 05 | ESP Front MK60 | A2C59514447 |
| Seat | Leon with ESP | 1P | 05 - | ESP Front/Allrad MK60 | A2C59514447 |
| Seat | Leon without ESP | 1P | 05 - | ABS MK70 | A2C59514447 |
| Seat | Toledo | 1M | 99 - 02 | ESP 20 | A2C59514447 |
| Seat | Toledo | 1M | 02 - 05 | ESP Front/Allrad MK60 | A2C59514447 |
| Seat | Toledo with ESP | 5P | 05 - | ESP Front/Allrad MK60 | A2C59514447 |
| Seat | Toledo without ESP | 5P | 05 - | ABS MK70 | A2C59514447 |
| Skoda | Fabia | 6Y | 99 - 04 | ESP 5.7 Front / Allrad | A2C59514447 |
| Skoda | Fabia | 6Y | 04 - 07 | ESP 8 Front / Allrad | A2C59514447 |
| Skoda | Octavia | 1U | 96 - 02 | ESP 20 | A2C59514447 |
| Skoda | Octavia | 1U | 02 - 04 | ESP Front / Allrad MK60 | A2C59514447 |
| Skoda | Octavia II with ESP | 1Z | 04 - | ESP Front / Allrad MK60 | A2C59514447 |
| Skoda | Octavia II without ESP | 1Z | 04 - | ABS MK70 | A2C59514447 |
| Skoda | Superb | 3U | 02 - 04 | ABS/ESP Front | A2C59514447 |
| Skoda | Superb II | 3T | 08 - | ESP Front/Allrad MK60 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SAS - Steering Angle Sensor

| Make | Model | Body/Chassis | From/To | System | Harness Required |
|------|--|-------------------------|---------|------------------------------|------------------|
| VW | Beetle | 1C, 9C, 1Y (A Platform) | 98 - 01 | ESP 20 | A2C59514447 |
| VW | Beetle | 1C, 9C, 1Y (A Platform) | 01 - | ESP Front / Allrad MK60 | A2C59514447 |
| VW | Bora | 1K2 | 05 - | ESP Front / Allrad MK60 | A2C59514447 |
| VW | Caddy | 2K | 04 - | ESP Front / Allrad MK60 | A2C59514447 |
| VW | EOS | 1F | 05 - | ESP Front / Allrad MK60 | A2C59514447 |
| VW | Fox | 5Z1 | 04 - | ESP 8 Front / Allrad | A2C59514447 |
| VW | Golf 4motion/R32 | 1J | 98 - 01 | ESP 20 | A2C59514447 |
| VW | Golf 4motion/R32 | 1J | 01 - 04 | ESP Allrad MK60 | A2C59514447 |
| VW | Golf MK4 / Gti /Rabbit / Bora | 6E/6X | 98 - 01 | ESP 20 | A2C59514447 |
| VW | Golf MK4 / Gti /Rabbit / Bora (US Jetta) | 1J | 01 - 04 | ESP Front MK60 | A2C59514447 |
| VW | Golf MK5 4motion/R32 | 1K | 04 - | ESP Allrad MK60 | A2C59514447 |
| VW | Golf MK5 With ESP | 1K | 04 - | ESP Front MK60 | A2C59514447 |
| VW | Golf MK5 without ESP | 1K | 04 - | ABS MK70 | A2C59514447 |
| VW | Golf Plus | 5M1 | 05 - | ESP Front MK60 | A2C59514447 |
| VW | Jetta | 1K2 | 05 - | ESP Front MK60 | A2C59514447 |
| VW | Lupo | | 99 - | ESP 20 | A2C59514447 |
| VW | Passat | B5 (3B) | 97 - 02 | ABS/ESP Front | A2C59514447 |
| VW | Passat | B5 (3B) | 02 - 05 | ABS/ESP Front | A2C59514447 |
| VW | Passat | B6 (3C) | 05 - | ESP 440 C2 | A2C59514447 |
| VW | Passat 4motion | B5 (3B) | 97 - 02 | ABS/ESP Allrad | A2C59514447 |
| VW | Passat 4motion | B5 (3B) | 02 - 05 | ABS/ESP Allrad | A2C59514447 |
| VW | Passat 4motion | B6 (3C) | 05 - | ESP 440 C2 | A2C59514447 |
| VW | Phaeton | D3 (3D) | 03 - | ESP 5.7 Front / Allrad | A2C59514447 |
| VW | Polo | 9N | 02 - 05 | ESP 5.7 Front | A2C59514447 |
| VW | Polo | 9N | 05 - | ESP 8 Front / Allrad | A2C59514447 |
| VW | Polo | 9N | 05 - | ESP Front MK60 | A2C59514447 |
| VW | Sharan | 7M | 98 - | ESP 20 | A2C59514447 |
| VW | Touareg | 7L | 03 - 06 | ESP Allrad MK25 | A2C59514447 |
| VW | Touareg | 7L | 03 - 06 | ESP Allrad MK60 | A2C59514447 |
| VW | Touareg | 7L | 07 - | ESP Allrad MK25 | A2C59514447 |
| VW | Touran | 1T | 05 - | ESP Front/Allrad MK60 | A2C59514447 |
| VW | Transporter | 7D, 70 | 96 - 03 | ESP 5.3 T4 front | A2C59514447 |
| VW | Transporter T5 | 7H, 7J | 03 - | ESP Front/Allrad MK25/MK25E1 | A2C59514447 |

FASTCHECK SERVICE

| Make | Model | From/To | System | Harness Required |
|------------|-------------------------|------------|---|--------------------------------|
| Alfa Romeo | 147 | 00 - 07 | Service Interval Reset - Mannesman VDO instrument panel | A2C59514447 |
| Alfa Romeo | 159 | 05 - | Service Interval Reset - Siemens 2 Instrument panel | A2C59514447 |
| Alfa Romeo | 159 (1.9 MJET 16V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Alfa Romeo | 159 (1.9 MJET 8V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Alfa Romeo | 159 (2.4 MJET) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Alfa Romeo | Brera | 05 - | Service Interval Reset - Siemens 2 Instrument panel | A2C59514447 |
| Alfa Romeo | GT | 04 - | Service Interval Reset - Mannesman VDO instrument panel | A2C59514447 |
| Alfa Romeo | MiTo | 08 - | Service Interval Reset - DENSO Single-zone climate control (EP) | A2C59514447 |
| Alfa Romeo | MiTo (1.3 JTD) | 08 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Alfa Romeo | MiTo (1.6 MJET) | 08 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Alfa Romeo | Spider (939) | 07 - | Service Interval Reset - Siemens 2 Instrument panel | A2C59514447 |
| Audi | 80/Cabrio/Coupe/Quattro | 94 - 96 | KWP1281 | A2C59514447 (with A2C59512079) |
| Audi | A2 | 01 - 06 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 96 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A3 | 04 - 08 | CAN | A2C59514447 |
| Audi | A3 | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | A4 | 95 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A4 | 04 - 08 | CAN | A2C59514447 |
| Audi | A4 | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | S4 | 92 - 02 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| Audi | S4 | 04 - 08 | CAN | A2C59514447 |
| Audi | S4 | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | A5 | 08 - | CAN | A2C59514447 |
| Audi | A5 | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | S5 | 08 - | CAN | A2C59514447 |
| Audi | S5 | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | A6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A6 | 04 - 08 | CAN | A2C59514447 |
| Audi | A6 | 09 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | S6 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S6 | 04 - 08 | CAN | A2C59514447 |
| Audi | S6 | 09 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | Allroad Quattro | 01 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | Q5 | 09 - | CAN | A2C59514447 |
| Audi | Q7 | 06 - | CAN | A2C59514447 |
| Audi | Q7 | 09 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | A8 | 94 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | A8 | 04 - | CAN | A2C59514447 |
| Audi | R8 | 07 - | CAN | A2C59514447 |
| Audi | R8 | 09 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | S8 | 97 - 04 | KWP1281/KW2000 | A2C59514447 |
| Audi | S8 | 04 - | CAN | A2C59514447 |
| Audi | TT | 00 - 07 | KWP1281/KW2000 | A2C59514447 |
| Audi | TT | 07 - | CAN | A2C59514447 |
| Audi | TT | 08 - | Advanced Maintenance Concept (CAN) | A2C59514447 |
| Audi | 100 | 94 - 97 | KWP1281/KW2000 | A2C59514447 (with A2C59512079) |
| BMW | 1 Series (E81/E87) | 04 - 03/07 | CBS | A2C59514447 |
| BMW | 1 Series (E81/E87) | 04 - 03/07 | Annual Distance | A2C59514447 |
| BMW | 1 Series (E81/E87) | 04 - 03/07 | Battery Change | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SERVICE

| Make | Model | From/To | System | Harness Required |
|---------|----------------------------|------------|--|--------------------------------|
| BMW | 1 Series (E81/E87) | 03/07 - | CBS (D-CAN) | A2C59514447 |
| BMW | 1 Series (E81/E87) | 03/07 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | 1 Series (E81/E87) | 03/07 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | 3 Series (E30) | 88 - 91 | Analogue | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E36) | 91 - 99 | Analogue | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E46) | 98 - 05 | Digital or Analogue | A2C59514447 (with A2C59512084) |
| BMW | 3 Series (E90/E91/E92/E93) | 05 - 03/07 | CBS | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 05 - 03/07 | Annual Distance | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 05 - 03/07 | Battery Change | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | CBS (D-CAN) | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | 5 Series (E34) | 88 - 97 | Analogue | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E39) | 97 - 03 | Digital or Analogue | A2C59514447 (with A2C59512084) |
| BMW | 5 Series (E60/E61) | 04 - 03/07 | CBS | A2C59514447 |
| BMW | 5 Series (E60/E61) | 04 - 03/07 | Annual Distance | A2C59514447 |
| BMW | 5 Series (E60/E61) | 04 - 03/07 | Battery Change | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | CBS (D-CAN) | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 03/07 | CBS | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 03/07 | Annual Distance | A2C59514447 |
| BMW | 6 Series (E63/E64) | 05 - 03/07 | Battery Change | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | CBS (D-CAN) | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | 6 Series (E63/E64) | 03/07 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | 7 Series (E38) | 95 - 02 | Digital or Analogue | A2C59514447 (with A2C59512084) |
| BMW | 7 Series (E65) | 02 - 03/07 | CBS | A2C59514447 |
| BMW | 7 Series (E65) | 02 - 03/07 | Annual Distance | A2C59514447 |
| BMW | 7 Series (E65) | 02 - 03/07 | Battery Change | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | CBS (D-CAN) | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | 8 Series (E31) | 91 - 97 | Analogue | A2C59514447 (with A2C59512084) |
| BMW | X3 (E83) | 03 - | Digital | A2C59514447 |
| BMW | X5 (E53) | 00 - | Digital or Analogue | A2C59514447 (with A2C59512084) |
| BMW | X5 (E70) | 06 - | CBS (D-CAN) | A2C59514447 |
| BMW | X5 (E70) | 06 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | X5 (E70) | 06 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | CBS (D-CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | Annual Distance (D-CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | Battery Change (D-CAN) | A2C59514447 |
| BMW | Z3 (E36) | 96 - 02 | Digital or Analogue | A2C59514447 (with A2C59512084) |
| BMW | Z4 (E85) | 03 - | Digital | A2C59514447 |
| BMW | Z8 (E52) | 99 - 04 | Analogue | A2C59514447 (with A2C59512084) |
| Citroen | C4 Grand Picasso | 07 - | PSA Service Reset | A2C59514447 |
| Fiat | 500 | 07 - | Service Interval Reset - MARELLI Instrument panel (EP) 2 | A2C59514447 |
| Fiat | 500 (1.3 JTD) | 07 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Bravo '07 | 07 - | Service Interval Reset - Siemens 3 Instrument panel | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SERVICE

| Make | Model | From/To | System | Harness Required |
|------------|---|---------|--|------------------|
| Fiat | Bravo '07 (1.9 MJET 8V) | 07 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Croma '05 | 05 - | Service Interval Reset - Marelli 2 instrument panel | A2C59514447 |
| Fiat | Croma '05 (1.9 MJET 16V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Croma '05 (1.9 MJET 8V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Croma '05 (MJET 20V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Doblo (1.3 JTD) | 00 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Ducato III | 07 - | Service Interval Reset - Instrument panel | A2C59514447 |
| Fiat | Ducato III | 07 - | Oil Change Reset - Instrument panel | A2C59514447 |
| Fiat | Idea | 04 - | Service Interval Reset - Marelli instrument panel - comfort | A2C59514447 |
| Fiat | Idea (1.3 JTD) | 04 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Palio RST (1.3 JTD) | 01 - 02 | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Palio RST2 | 02 - | Service Interval Reset - Marelli instrument panel - Palio RST2 | A2C59514447 |
| Fiat | Panda '03 | 03 - | Service Interval Reset - Marelli instrument panel | A2C59514447 |
| Fiat | Panda '03 (1.3 JTD) | 03 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Punto '03 | 03 - 05 | Service Interval Reset - Marelli instrument panel - comfort | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) | 05 - | Service Interval Reset - Marelli Cluster (EP) | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) (1.3 MJET 16V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) (1.9 MJET 8V) | 05 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Fiat | Stilo | 01 - 07 | Service Interval Reset - Visteon instrument panel | A2C59514447 |
| Ford | Galaxy (with VW engine) | 95 - 00 | KWP1281 / KW2000 | A2C59514447 |
| Ford | Fiesta VI (1.6 TDCi) | 08 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Ford | Fusion II (1.6 TDCi) | 09 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Ford | Ka II (1.3 TDCi) | 08 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Ford | Mondeo IV (2.0 TDCi) | 07 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Ford | Transit (2.0 TDCi) | 06 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| GM | Agila-A | 00 - 08 | InstAgil | A2C59514447 |
| GM | Astra-G | 98 - 04 | Instr30 | A2C59514447 |
| GM | Astra-H | 04 - | CAN IPC | A2C59514447 |
| GM | Corsa-C | 01 - 06 | Instr43 | A2C59514447 |
| GM | Corsa-D | 06 - | CAN IPC | A2C59514447 |
| GM | Meriva-A | 03 - 08 | Instr43 | A2C59514447 |
| GM | Signum | 01 - | CAN IPC | A2C59514447 |
| GM | Signum | 01 - | Long-Life Oil Reset | A2C59514447 |
| GM | Tigra-B | 05 - 08 | Instr43 | A2C59514447 |
| GM | Vectra-C | 01 - | CAN IPC | A2C59514447 |
| GM | Vectra-C | 01 - | Long-Life Oil Reset | A2C59514447 |
| GM | Zafira-A | 98 - 05 | Instr30 | A2C59514447 |
| GM | Zafira-B | 05 - | CAN IPC | A2C59514447 |
| Lancia | Musa (Marelli instrument panel - comfort) | 04 - | | A2C59514447 |
| Lancia | Thesis (Nippon Seiki instrument panel) | 02 - | | A2C59514447 |
| Lancia | Ypsilon (Siemens instrument panel) | 03 - | | A2C59514447 |
| Land Rover | Freelander II (L359) | 07 - | Service Reset | A2C59514447 |
| Land Rover | Freelander II (L359) (2.2 TDCi) | 07 - | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | Service Reset | A2C59514447 |
| Land Rover | Discovery III (L319) (TDV6) | 05 - 09 | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Land Rover | Range Rover (L322) | 07 - 09 | Service Reset | A2C59514447 |
| Land Rover | Range Rover (L322) (TDV8) | 07 - 09 | Oil Degradation Counter Reset (DPF only) | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | Service Reset | A2C59514447 |
| Land Rover | Range Rover Sport (L320) (TDV6) | 05 - 09 | Oil Degradation Counter Reset (DPF only) | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SERVICE

| Make | Model | From/To | System | Harness Required |
|----------|--------------------------------------|------------|-------------------------|---|
| Mercedes | A Class (W169) | 04 - 12/05 | Assyst Plus | A2C59514447 |
| Mercedes | B Class (W245) | 05 - 12/05 | Assyst Plus | A2C59514447 |
| Mercedes | C Class (W202) | 96 - 00 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | C Class (W203) | 00 - 03 | FSS | A2C59514447 |
| Mercedes | CL (W215) | 99 - 00 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | CL (W215) | 00 - 05 | FSS | A2C59514447 |
| Mercedes | CLK (W208) | 98 - 04 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | CLS (W219) | 04 - | Assyst Plus | A2C59514447 |
| Mercedes | E Class (W210) | 96 - 02 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | E Class (W211) | 02 - | Assyst Plus | A2C59514447 |
| Mercedes | ML (W163) | 97 - 05 | FSS | A2C59514447 |
| Mercedes | ML (W164) | 05 - | Assyst Plus | A2C59514447 |
| Mercedes | R Class (V251) | 05 - | Assyst Plus | A2C59514447 |
| Mercedes | S Class (W140) | 97 - 99 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | S Class (W220) | 99 - 05 | FSS | A2C59514447 |
| Mercedes | S Class (W221) | 05 - | Assyst Plus | A2C59514447 |
| Mercedes | SL (R129) | 95 - 02 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | SL (R230) | 01 - 03 | FSS | A2C59514447 |
| Mercedes | SLK (R170) | 98 - 01 | FSS | A2C59514447 (with A2C59512083) |
| Mercedes | SLK (R171) | 04 - | Assyst Plus | A2C59514447 |
| Mercedes | Sprinter (W901 / W902 / W903 / W904) | 95 - 02 | FSS | A2C59514447 (with A2C59512082 if no J1962*) |
| Mercedes | Sprinter (W906) | 06 - | FSS | A2C59514447 |
| MG Rover | 75 | 99 - 02 | | A2C59514447 |
| MINI | MINI (R50 / R53) | 00 - 07 | Digital | A2C59514447 |
| MINI | MINI (R55 / R56 / R67) | 09/06 - | CBS (D-CAN) | A2C59514447 |
| MINI | MINI (R55 / R56 / R67) | 09/06 - | Annual Distance (D-CAN) | A2C59514447 |
| MINI | MINI (R55 / R56 / R67) | 09/06 - | Battery Change (D-CAN) | A2C59514447 |
| Peugeot | 3008 | 09 - | PSA Service Reset | A2C59514447 |
| Peugeot | 5008 | 07 - | PSA Service Reset | A2C59514447 |
| Saab | 9-3 | 98 - 02 | | A2C59514447 |
| Saab | 9-5 | 97 - 02 | | A2C59514447 |
| Seat | Alhambra | 96 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Altea | 04 - | CAN | A2C59514447 |
| Seat | Arosa | 97 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Cordoba | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Ibiza | 93 - | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 00 - 04 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Leon | 04 - | CAN | A2C59514447 |
| Seat | Toledo | 92 - 05 | KWP1281 / KW2000 | A2C59514447 |
| Seat | Toledo III | 04 - | CAN | A2C59514447 |
| Skoda | Fabia | 00 - 07 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Fabia II | 07 - | CAN | A2C59514447 |
| Skoda | Octavia | 96 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Octavia II | 04 - | CAN | A2C59514447 |
| Skoda | Roomster | 06 - | CAN | A2C59514447 |
| Skoda | Superb | 02 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| Skoda | Yeti | 10 - | CAN | A2C59514447 |
| Volvo | 850 | 93 - 97 | | A2C59514447 |
| Volvo | S40 | 97 - 98 | | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK SERVICE

| Make | Model | From/To | System | Harness Required |
|-------|--------------------------|---------|------------------|--------------------------------|
| Volvo | V40 | 97 - 98 | | A2C59514447 |
| Volvo | S70 | 97 - 98 | | A2C59514447 |
| Volvo | V70 | 97 - 98 | | A2C59514447 |
| VW | Amorak | 10 - | CAN | A2C59514447 |
| VW | Beetle | 99 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Bora | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Bora | 05 - | CAN | A2C59514447 |
| VW | Cabrio | 95 - 02 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 92 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Caddy | 05 - | CAN | A2C59514447 |
| VW | Corrado | 91 - 95 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | EOS | 05 - | CAN | A2C59514447 |
| VW | Eurovan | 99 - 03 | KWP1281 / KW2000 | A2C59514447 |
| VW | Golf/GTI | 92 - 03 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Golf/GTI | 03 - | CAN | A2C59514447 |
| VW | Golf VI (5K) | 09 - | CAN | A2C59514447 |
| VW | Golf Plus | 05 - | CAN | A2C59514447 |
| VW | Golf Plus (52) | 09 - | CAN | A2C59514447 |
| VW | Jetta | 92 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Jetta | 05 - | CAN | A2C59514447 |
| VW | Lupo | 98 - 05 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 94 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Passat | 05 - 08 | CAN | A2C59514447 |
| VW | Passat VI (B6 - 3C) | 08 - | CAN | A2C59514447 |
| VW | Phaeton | 03 - | KWP1281 / KW2000 | A2C59514447 |
| VW | Polo | 98 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Scirocco III | 09 - | CAN | A2C59514447 |
| VW | Sharan | 95 - | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Touareg | 03 - 06 | KWP1281 / KW2000 | A2C59514447 |
| VW | Touareg | 07 - | CAN | A2C59514447 |
| VW | Touran | 03 - | CAN | A2C59514447 |
| VW | Transporter/Caravelle | 92 - 04 | KWP1281 / KW2000 | A2C59514447 (with A2C59512079) |
| VW | Transporter/Caravelle T5 | 04 - | CAN | A2C59514447 |
| VW | Vento | 92 - 98 | KWP1281 / KW2000 | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

FASTCHECK TPMS

| Make | Model | From/To | System | Harness Required |
|------------|----------------------------|------------|---------------------------------------|------------------|
| BMW | 1 Series (E81/E82/E87/E88) | 03/07 - | RDC (D-CAN) | A2C59514447 |
| BMW | 3 Series (E46) | 98 - 03 | RDC | A2C59514447 |
| BMW | 3 Series (E90/E91/E92/E93) | 03/07 - | RDC (D-CAN) | A2C59514447 |
| BMW | 5 Series (E39) | 96 - 98 | DDS | A2C59514447 |
| BMW | 5 Series (E39) | 98 - 03 | RDC | A2C59514447 |
| BMW | M5 (E39) | 98 - 03 | DDS | A2C59514447 |
| BMW | 5 Series (E60/E61) | 03/07 - | RDC (D-CAN) | A2C59514447 |
| BMW | 7 Series (E38) | 94 - 01 | RDC | A2C59514447 |
| BMW | 7 Series (E38) | 99 - 01 | DDS | A2C59514447 |
| BMW | 7 Series (E65) | 01 - 03/07 | RDC 65 | A2C59514447 |
| BMW | 7 Series (E65) | 03/07 - | RDC 65 (D-CAN) | A2C59514447 |
| BMW | X5 (E53) | 00 - 06 | DDS | A2C59514447 |
| BMW | X5 (E53) | 00 - 06 | RDC 53 | A2C59514447 |
| BMW | X5 (E70) | 06 - | RDC (D-CAN) | A2C59514447 |
| BMW | X6 (E71) | 08 - | RDC (D-CAN) | A2C59514447 |
| Citroen | C4 | 04 - | Schrader TPMS | A2C59514447 |
| Citroen | C5 | 99 - 05 | Schrader TPMS | A2C59514447 |
| Citroen | C5 II | 04 - | Schrader TPMS | A2C59514447 |
| Citroen | C6 | 06 - | Schrader TPMS | A2C59514447 |
| Citroen | C8 | 02 - | Schrader TPMS | A2C59514447 |
| Fiat | Punto '05 (Grande Punto) | 05 - | TRW Tyre Pressure Control (EP) | A2C59514447 |
| Fiat | Ulysse | 94 - 05 | Schrader TPMS | A2C59514447 |
| Ford | Explorer | 04 - | TPMS | A2C59514447 |
| Ford | Focus | 04 - | TPMS | A2C59514447 |
| Ford | Focus C-Max | 03 - | TPMS | A2C59514447 |
| Ford | Expedition | 05 - | TPMS | A2C59514447 |
| GM | Vectra-C | 02 - | TPMS | A2C59514447 |
| GM | Signum | 02 - | TPMS | A2C59514447 |
| GM | Astra-H | 04 - | TPMS | A2C59514447 |
| GM | Zafira-B | 05 - | TPMS | A2C59514447 |
| Lancia | Phedra | 02 - 06 | Schrader TPMS | A2C59514447 |
| Land Rover | Discovery III (L319) | 05 - 09 | TPMS | A2C59514447 |
| Land Rover | Range Rover (L322) | 07 - 09 | TPMS | A2C59514447 |
| Land Rover | Range Rover Sport (L320) | 05 - 09 | TPMS | A2C59514447 |
| MINI | MINI (R50 / R52 / R53) | 00 - 07 | DDS | A2C59514447 |
| MINI | MINI (R55 / R56 / R57) | 06 - | RDC (D-CAN) | A2C59514447 |
| Peugeot | 307 II | 05 - | Schrader TPMS | A2C59514447 |
| Peugeot | 407 | 04 - | Schrader TPMS | A2C59514447 |
| Peugeot | 607 | 99 - | Schrader TPMS | A2C59514447 |
| Peugeot | 607 II | 04 - | Schrader TPMS | A2C59514447 |
| Peugeot | 807 | 02 - | Schrader TPMS | A2C59514447 |
| Renault | Clio III | 05 - | Central Body Electrics - Renault TPMS | A2C59514447 |
| Renault | Espace IV | 03 - | Central Body Electrics - Renault TPMS | A2C59514447 |
| Renault | Laguna II | 00 - | Central Body Electrics - Renault TPMS | A2C59514447 |
| Renault | Megane II | 02 - | Central Body Electrics - Renault TPMS | A2C59514447 |
| Renault | Scenic II | 03 - | Central Body Electrics - Renault TPMS | A2C59514447 |
| Renault | Vel Satis | 00 - | Central Body Electrics - Renault TPMS | A2C59514447 |

Due to model changes, dates may not be precise. Try other leads or systems before contacting product support.
 Petrol vehicles MY2000 on (diesel MY2004 on) should be EOBD compliant and can be diagnosed via EOBD for emissions data.

TPMS Module

| Make | Model | From/To | OE Number of Sensor | Marking on Sensor Tg1B | Marking on Sensor Tg1C | Order Number Replacement Sensor | Order Number Service-Kit Tg1B | Order Number Service-Kit Tg1C |
|---------------|----------------------|------------|---------------------|------------------------|------------------------|---------------------------------|-------------------------------|-------------------------------|
| Citroen | C4 | 04 - | 5430T4 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Citroen | C5 | 04 - | 5430T4 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Citroen | C6 | 04 - | 5430T4 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Citroen | C8 | 06/04 - | 5430T4 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Fiat | 2F Nuovo Ulysee | 01 - 12/10 | 9681102280 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Ford | Galaxy | 06 - | 8G92 1A159-AC | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Ford | S-Max | 06 - | 8G92 1A159-AC | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Ford | Mondeo | 07 - | 8G92 1A159-AC | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Hyundai | i20 | 09/08 - | 52933 1J000 | --- | S180052012 | S180084710Z | S180014531A | S180084510A |
| Hyundai | iX20 | 2010 - | 52933 1J000 | --- | S180052012 | S180084710Z | S180014531A | S180084510A |
| Hyundai | i30 | 07 - | 52933 2L600 | S180030002 | --- | S180014820Z | S180014531A | --- |
| Jaguar | X350 Limousine | 06 - | C2Z15016 | S120123002 | S180052022 | S180084770Z | S180014561A | S180084520A |
| Jaguar | X-Type | 07 - | C2Z15016 | S120123002 | S180052022 | S180084770Z | S180014561A | S180084520A |
| Jaguar | XK | 06 - | C2Z15016 | S120123002 | S180052022 | S180084770Z | S180014561A | S180084520A |
| Kia | Cee'd / Cee'd SW | 07 - | 52933 2L600 | S180030002 | --- | S180014820Z | S180014531A | --- |
| Kia | Soul 1.6 CVVT | 10/08 - | 52933 1J000 | --- | S180052012 | S180084710Z | S180084510A | --- |
| Kia | Venga | 10/08 - | 52933 1J000 | --- | S180052012 | S180084710Z | S180084510A | --- |
| Kia | Sorento | 05/09 - | 52933 1J000 | --- | S180052012 | S180084710Z | S180084510A | --- |
| Lancia | TC Phedra | 01 - 12/10 | 9681102280 | S120123004 | --- | S180014805Z | S180014531A | --- |
| Land Rover | Range Rover | 05 - | LR031712 | S120123002 | S180052022 | A2C59511308 | S180014561A | S180084520A |
| Land Rover | Discovery | 05 - | LR031712 | S120123002 | S180052022 | A2C59511308 | S180014561A | S180084520A |
| Land Rover | FreeLander | 05 - | LR021935 | S120123002 | S180052022 | S180084770Z | S180014561A | S180084520A |
| Land Rover | Evoque | 7/11 - | LR031712 | S120123002 | S180052022 | A2C59511308 | S180014561A | S180084520A |
| Mazda | 3 | 09 - | BBP337140B | S120123010 | S180052018 | S180084720Z | S180014531A | S180084540A |
| Mazda | 5 | 10 - | BBP337140B | S120123010 | S180052018 | S180084720Z | S180014531A | S180084540A |
| Mazda | 6 | 08 - | BBP337140B | S120123010 | S180052018 | S180084720Z | S180014531A | S180084540A |
| Mazda | MX5 | 3/10 - | BBP337140B | --- | S180052018 | S180084720Z | --- | S180084540A |
| Mazda | CX7 | 09 - | BBP337140B | S120123010 | S180052018 | S180084720Z | S180014531A | S180084540A |
| Mercedes Benz | M-Class (W164) | 05 - 07/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | E-Class (W211) | 05 - 03/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | S-Class (W221) | 05 - 06/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | CLS (W219) | 05 - 07/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | SL (W230) | 05 - 07/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | R-Class (W251) | 05 - 07/09 | 002 540 67 17 | S122228002 | --- | S180014730Z | S180014541A | --- |
| Mercedes Benz | Sprinter NVC 3 (906) | 06 - | 002 540 95 17 | S122228002 | --- | A2C59511309 | S180014541A | --- |
| Mercedes Benz | Vito NVC 2 (639) | 06 - | 002 540 95 17 | S122228002 | --- | A2C59511309 | S180014541A | --- |
| Peugeot | 1007 (KM) | 05 - 12/09 | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 207 CC | 04 - | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 307 | 04 - | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 407 / 407 SW | 04 - | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 607 | 04 - 09/10 | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 508 / 508 SW | 10 - | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Peugeot | 807 | 04 - | 5430T4 | S120120001 | --- | S180014805Z | S180014531A | --- |
| Renault | Megane II | 02 - 11/08 | 7701 476 662 | S120123006 | --- | S180014810Z | S180014500A | --- |
| Renault | Scenic II | 02 - 04/09 | 7701 476 662 | S120123006 | --- | S180014810Z | S180014500A | --- |
| Renault | Megane III | 08 - | 40 70 004 35 R | --- | S180052004 | S180084700Z | --- | S180084500A |
| Renault | Scenic III | 04/09 - | 40 70 004 35 R | --- | S180052004 | S180084700Z | --- | S180084500A |
| Renault | Laguna III | 08 - | 40 70 004 35 R | --- | S180052004 | S180084700Z | --- | S180084500A |
| Renault | Latitude | 11 - | 40 70 004 35 R | --- | S180052004 | S180084700Z | --- | S180084500A |

TPMS Module

| Make | Model | From/To | OE Number of Sensor | Marking on Sensor TG1B | Marking on Sensor TG1C | Order Number Replacement Sensor | Order Number Service-Kit TG1B | Order Number Service-Kit TG1C |
|------------|-------------------------|------------|---------------------|---------------------------|---------------------------|------------------------------------|----------------------------------|----------------------------------|
| Volkswagen | Passat / Passat Synchro | 06 - 10/10 | 1K0 907 253 C | S122215002 | --- | S180014701Z | S180014511A | --- |
| Volkswagen | New Beetle | 06 - 07/10 | 1K0 907 253 C | S122215002 | --- | S180014701Z | S180014511A | --- |
| Volvo | S60 | 3/10 - | 31302096 | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Volvo | S 80 | 07 - | 31302096 | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Volvo | V60 | 11/10 - | 31302096 | --- | S180052020 | S180084730Z | --- | S180084520A |
| Volvo | V 70 | 07 - | 31302096 | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Volvo | XC 60 | 07 - | 31302096 | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |
| Volvo | XC 70 | 07 - | 31302096 | S122780002 | S180052020 | S180084730Z | S180014561A | S180084520A |

